

# REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 3673** Survey held at *West Hartlepool* Date, first Survey *18 July* Last Survey *20 July* 1876  
*457* on the *S.S. "Marmora"* Master \_\_\_\_\_

Official Number *58753*  
 TONNAGE under Tonnage Deck *606*  
 Ditto of Spar Deck, or Awning Deck *255*  
 Ditto of Poop *604*  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam  
 Engine Room  
 Reg. Tons as St' mer, cut on Bm.  
 Built at *Hartlepool* When built *1868* - *3*  
 Owners *J. Herold & Co.* Port belonging to *Hartlepool*  
 Residence *West Hartlepool*  
 By whom built *Denton* Destined Voyage *Baltic*  
 If Surveyed Afloat or in Dry Dock *Afloat in West Dock*

Length of Poop \_\_\_\_\_ ft. Ditto, Forecastle \_\_\_\_\_ ft. Ditto, Raised Quarter Deck \_\_\_\_\_ ft. Years assigned. *Classed A1*  
 Last Survey, No. *14724* Port *Lyon* S.S. *Apr. No. 2-75* 6/75

REPAIRS, OR EXAMINATION AS PER RULE *Damage caused by Ice*  
*Two bent shell plates taken out the same vessel & refitted, two fractured frames strengthened with corresponding angles over fractures & riveted through.*

Cause of Repairs to be clearly stated.

Present Condition of the  
 Decks *Good*  
 Waterways *"*  
 Comings *"*  
 Upper Deck Beams & Fastenings *Good*  
 Lower Deck Beams & Fastenings *"*  
 Planksheers  
 Sheerstrakes *Good*  
 Topsides *"*  
 Wales *"*  
 Plank (Bottom) and Counter *Good when seen*  
 Engine Room Skylights *Good*  
 General Observations, Opinion as to Class, &c. *Is now in a good & efficient state fit for the*  
*safe conveyance of dry & perishable goods & is from all parts of the world*  
*& may in my opinion remain as now classed A1*  
*S.S. Apr. No. 2-75*

Tree-nails *Good*  
 Breasthooks and Stems *Good*  
 Transoms, Painters, and Crutches *Good*  
 Timbers of the Frame at the openings *"*  
 Ditto Ditto at other places *"*  
 Keelsons *Not seen*  
 Clamps and Shelves  
 Ceiling *Good when seen*  
 Rudder *"*  
 Copper *When put on*  
 Caulking of Bottom, Deck, & Waterways *Good when seen*  
 Windlass and Capstan *Good*  
 Pumps *Good*  
 Boats *Good*  
 Masts, Yards, &c. *Good*  
 Condition, how ascertained *From Deck*  
 Sails *Good*  
 Anchors No. of *3 Bower 1 Stern 2 Kedge*  
 Cables *Good*  
 Hawser and Warps *Good*  
 Standing & Running Rigging *Good*  
 Scuppers *Good*  
 Cargo and Main Hatchways *Good*  
 Hatches *Good*

The Amount of Entry Fee ... £ *2 : 0 : 0* received by me, *J. M. Gladstone*  
 Special ... £ *1 : 1 : 0* 20 July 1876  
 Certificate (if required) ... £ : :  
 (Travelling Expenses, if any, £ *51*)  
 Committee's Minute *1 August 1876*  
 Character assigned *B*  
*J. M. Gladstone*  
*Surveyor to Lloyd's Register of British and Foreign Shipping.*



© 2019

Lloyd's Register Foundation

IRON 467-0370