

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** 3446 Survey held at Newport Date, first Survey 1876 Last Survey 29th July 1876
1203. on the S. S. "Monte Moro." Master Irving

Official Number	Tonnage under Tonnage Deck	1753	Built at	Newcastle	When built	1845	YEAR.	MONTH.
	Ditto of Spar Deck, or Awning Deck		Owners	Hell & Blenkinsop	Port belonging to	S. Shields		
	Ditto of Poop		Residence					
	Ditto of Raised Qr. Dk.		By whom built	Strain	Destined Voyage	Montreal		
	Ditto of Houses on Deck		Surveyed	Afloat or in Dry Dock	Newport Dry Dock			
	Ditto of Forecastle							
	Gross Tonnage	1474						
	Crew Space, as per Rule							
	Register Tonnage, cut on Beam							
	Engine Room							
Reg. Tons as St'mer, cut on Bm.	1154							
	Length of Poop	ft.	Ditto, Forecastle	ft.	Ditto, Raised Quarter Deck	ft.	Years assigned.	Character in Register Book.
	Last Survey, No.	15753	Port	Iron	Classed	100 A.1		

REPAIRS, OR EXAMINATION AS PER RULE.

Placed on Blocks in Dry Dock, for examination of bottom,
which appeared in excellent condition; . Cleaned & Coated
Externally with Patent Paint.

Cause of Repairs to be clearly stated.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings.

Lower Deck Beams & Fastenings.

Planksheers

Sheerstrakes

Topsides.

Wales.

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Vessel to far as seen, appears in good and efficient condition; eligible to remain as classed 100.A.B.

The Amount of Entry Fee £ : :

received by me,

Special ... £ / : :

~~Certificate (if required)~~£ : :

(Travelling Expenses, if any, £.....)

Committee's Minute

Character assigned

[3,000—9/5/76.]

(The Surveyors are requested not to write on or below the space for Committee's Minute.)



© 2019

Lloyd's Register
Foundation

IRON 467-0382

Monte Moro



© 2019

Lloyd's Register
Foundation