

# ANNUAL SURVEYS.

No. in Reg. Book. **No.** 6844 Survey held at London Date, first Survey \_\_\_\_\_ Last Survey Sept 14 1876  
 on the RN Amelia Ross Master \_\_\_\_\_  
 Tonnage 383 Built at Inverky When built 1867 11 mo.  
 By whom built Scott Owners Ross & Co  
 Port belonging to Inverky Business Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 15304 Port of Iron Classed A1 11.75  
 Present Condition of the Decks Good Freemasts Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Boated When put on now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom Scraped & Boated

She is now in an efficient state of repair and entitled to remain as classed

Senhouse Martindale

Committee's Minute 26 September 1876

Character assigned A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. in Reg. Book. **No.** 4116 Survey held at London Date, first Survey \_\_\_\_\_ Last Survey Sept 26 1876  
 on the S Pleiades Master \_\_\_\_\_  
 Tonnage 997 Built at Sturminster When built 1869 9 M  
 By whom built M. Millan Owners Shaw Savill & Co  
 Port belonging to London Southampton Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 15078 Port of Iron Classed A1 8.75  
 Present Condition of the Decks Good Freemasts Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Painted When put on now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom Scraped & Boated

She is now in an efficient state of repair & entitled to remain as classed.

Senhouse Martindale

Committee's Minute 26 September 1876

Character assigned A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18