

# ANNUAL SURVEYS. 16820 <sup>35699</sup>

No. in Reg. Book. **996** No. **15707** Survey held at London Date, first Survey Sept 1<sup>st</sup> 1876 Last Survey Sept 1<sup>st</sup> 1876  
 on the BK Annie Story Master R J Sharp  
 Tonnage 580 Built at Glasgow When built 1867 2 mo.  
 By whom built Stephen Owners R J Sharp  
 Port belonging to Liverpool Destined Voyage   
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 15707 Port of Iron  
 Present Condition of the  
 Decks Good Freemasts Ribs Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Canted When put on "  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom Scraped & Canted.

Classed A1 Years assigned 8.75 Character in Register Book SS Clyde m. 75

*She is now in an efficient state of repair and entitled to remain as classed*

Committee's Minute 15<sup>th</sup> Sept 1876

Character assigned A1

*Senhouse Martinide*

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. in Reg. Book. **348** No. **15066** Survey held at London Date, first Survey Aug 17 1876 Last Survey Aug 17 1876  
 on the BK Schepallion Master   
 Tonnage 602 Built at Lundee When built 1869 12 mo.  
 By whom built Brown Owners Shaw Saville & Co  
 Port belonging to London Destined Voyage   
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 15066 Port of Iron  
 Present Condition of the  
 Decks Good Freemasts Ribs Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Canted When put on None  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom Scraped & Canted

Classed A1 Years assigned 8.75 Character in Register Book SS Clyde m. 75

*She is now in an efficient state of repair and entitled to remain as classed*

Committee's Minute 15<sup>th</sup> Sept 1876

Character assigned A1

*Senhouse Martinide*

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18