

# ANNUAL SURVEYS.

Iron 16826 33670

Red 25.8.76

No. in Reg. Book. **No.** 451 on the **S.S. "John McIntyre"** Survey held at **London** Date, first Survey **10<sup>th</sup> Aug** Last Survey **12<sup>th</sup> Aug** 1876 Master **J. Wake**  
 Tonnage **985** Built at **Newcastle** When built **1863 - 8 mo**  
 By whom built **Palmer** Owners **J. Fenwick & Sons**  
 Port belonging to **London** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Pontoon Victoria Locks.**

Last Survey, No. **14796** Port of **Iron** Classed **Ad. 1.**  
 Present Condition of the Decks **Good** Treenails **Rivets** **Good** S.S. Lm. Net. **75.** Years assigned. **7-75** Character in Register Book.  
 Waterways **Good** Breasthooks and Stems **Good** Windlass and Capstan **Good**  
 Comings **Good** Transoms, Pointers, and Crutches **Good** Pumps **Good**  
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good** Boats **Good**  
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good** Masts, Yards, &c. **Good**  
 Planksheers **Good** Keelsons **Good** Condition, how ascertained **From deck**  
 Sheerstrakes **Good** Clamps and Shelves **Good** Sails **Good**  
 Topsides **Good** Ceiling **Good** Anchors, No. of **3 Bm 18<sup>th</sup> 2 Hage**  
 Wales **Good** Rudder **Good** Cables **Good**  
 Plate (Bottom) and Counter **Good** Copper or Y.M. Cent. When put on **63** Hawers and Warps **Good**  
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **Bottom and keel examined cleaned and coated with Paint, and Tallow, main hatch Comings renewed with 8/6 Plates, and the Rudder bushed.**

This Vessel is now in good and efficient condition and eligible to remain as Classed.

Committee's Minute **1<sup>st</sup> September** 1876 **Thos W. Blasely**  
 Character assigned **Ad. 1** Surveyor to Lloyd's Register of British and Foreign Shipping.

TRM

Certificate (if required) Paid 18

No. in Reg. Book. **No.** 1131 on the **Ship "Arctura"** Survey held at **London** Date, first Survey **15<sup>th</sup> Aug** Last Survey **Aug** 1876 Master **R. Hamilton**  
 Tonnage **1339** Built at **Greenock** When built **1869 - 7 mo**  
 By whom built **Steele** Owners **R. Hamilton**  
 Port belonging to **Liverpool** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Greens dry dock.**

Last Survey, No. **15292** Port of **Iron** Classed **Ad. 1.**  
 Present Condition of the Decks **Good** Treenails **Rivets** **Good** S.S. Cff. Net. **73.** Years assigned. **10-75** Character in Register Book.  
 Waterways **Good** Breasthooks and Stems **Good** Windlass and Capstan **Good**  
 Comings **Good** Transoms, Pointers, and Crutches **Good** Pumps **Good**  
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good** Boats **Good**  
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good** Masts, Yards, &c. **Good**  
 Planksheers **Good** Keelsons **Good** Condition, how ascertained **From deck**  
 Sheerstrakes **Good** Clamps and Shelves **Good** Sails **Good**  
 Topsides **Good** Ceiling **Good** Anchors, No. of **3 Bm 18<sup>th</sup> 2 Hage**  
 Wales **Good** Rudder **Good** Cables **Good**  
 Plate (Bottom) and Counter **Good** Copper or Y.M. Cent. When put on **69** Hawers and Warps **Good**  
 Engine Room Skylights **Good** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **Bottom and keel sighted cleaned and coated with Paint, and Tallow, and the topsides with Paint.**

This Vessel is now in good and efficient condition and eligible to remain as Classed.

Committee's Minute **1<sup>st</sup> September** 1876 **Thos W. Blasely**  
 Character assigned **Ad. 1** Surveyor to Lloyd's Register of British and Foreign Shipping.

TRM

Certificate (if required) Paid 18