

ANNUAL SURVEYS.

No. in Reg. Book. **25199** Survey held at **Liverpool** Date, first Survey **Aug 21st** Last Survey **Aug 21st 1876**
 on the Ship **"Bann"** Master **A. B. Rae.**
 Tonnage **1650** Built at **Sunderland** When built **1875 - 7 mo.**
 By whom built **Oswald** Owners **J. Nourse.**
 Port belonging to **London** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Brunswick Dry Dock.**

Last Survey, No. **15810** Port of **Liverpool** Classed **100 AL.**
 Present Condition of the Decks **Good** **Greenails Rivets Good** **8.75.**
 Waterways **"** **Breasthooks and Stemson**
 Comings **"** **Transoms, Pointers, and Crutches**
 Upper Deck Beams & Fastenings **"** **Timbers of the Frame at the Openings** **"**
 Lower Deck Beams & Fastenings **"** **Ditto ditto at other places** **"**
 Planksheers **"** **Keelsons** **"**
 Sheerstrakes **"** **Clamps and Shelves**
 Topsides **"** **Ceiling** **"**
 Wales **"** **Rudder** **"**
 Plank (Bottom) and Counter **"** **Copper or Y.M. Cement When put on 75.**
 Engine Room Skylights **✓** Coal Bunker, Openings, Lids, &c. **✓** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint. Vessel is now in a good and efficient condition eligible in my opinion to remain as Classed.

Committee's Minute **Liverpool Sep^r 5th 1876.** **T. Shilston.**
 Character assigned **100 AL.** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** **18**

No. **25199** Survey held at **Liverpool** Date, first Survey **Aug 22nd** Last Survey **Aug 23rd 1876**
 on the Ship **"British Ambassador"** Master **J. Davis.**
 Tonnage **1794** Built at **Liverpool** When built **1873 - 8 mo.**
 By whom built **Potter.** Owners **British Ship Owners Co. Limited.**
 Port belonging to **Liverpool** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Queens Dry Dock.**

Last Survey, No. **15139** Port of **Liverpool** Classed **100 AL.**
 Present Condition of the Decks **Good** **Greenails Rivets Good** **9.75.**
 Waterways **"** **Breasthooks and Stemson**
 Comings **"** **Transoms, Pointers, and Crutches**
 Upper Deck Beams & Fastenings **"** **Timbers of the Frame at the Openings** **"**
 Lower Deck Beams & Fastenings **"** **Ditto ditto at other places** **"**
 Planksheers **"** **Keelsons** **"**
 Sheerstrakes **"** **Clamps and Shelves**
 Topsides **"** **Ceiling** **"**
 Wales **"** **Rudder** **"**
 Plank (Bottom) and Counter **"** **Copper or Y.M. Cement When put on 73.**
 Engine Room Skylights **✓** Coal Bunkers, Openings, Lids, &c. **✓** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint. Vessel is now in a good and efficient condition eligible in my opinion to remain as Classed.

Committee's Minute **Liverpool Sep^r 5th 1876.** **T. Shilston.**
 Character assigned **100 AL.** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** **18**