

# ANNUAL SURVEYS.

16868 11.8.76  
35.662

No. in Reg. Book. **677** No. **14577** Survey held at London Date, first Survey \_\_\_\_\_ Last Survey August 5 1876  
 on the S Christian M'Aslan Master Jaylor  
 Tonnage 56 Built at Greenock When built 1869 - S M  
 By whom built Scott Owners Allison & Co  
 Port belonging to Glasgow Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 14577 Port of Iron Classed A Years assigned. 5.75 Character in Register Book. SS Glasgow 1.75

Present Condition of the Decks <u>good</u>	Treenails <u>Rivets</u>	<u>good</u>	Windlass and Capstan
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	<u>"</u>	Pumps
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	<u>"</u>	Boats
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	<u>"</u>	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	<u>"</u>	Condition, how ascertained <u>sufficient</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	<u>"</u>	Sails <u>where</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	<u>"</u>	Anchors, No. of <u>3 Bars &amp; Wedge</u> <u>they</u>
Topsides <u>"</u>	Ceiling <u>"</u>	<u>"</u>	Cables <u>could</u>
Wales <u>"</u>	Rudder <u>"</u>	<u>"</u>	Hawsers and Warps <u>be seen</u>
Plank (Bottom) and Counter <u>"</u>	Copper or <u>Y.M.</u> Painted When put on <u>new</u>	<u>"</u>	Standing and Running Rigging <u>good</u>
Engine Room Skylights <u>✓</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	<u>good</u>	Cargo and Main Hatchways <u>good</u>
Coal Bunker, Openings, Lids, &c. <u>✓</u>	Scuppers <u>good</u>	<u>good</u>	Hatches <u>good</u>

*at present the bottom scraped  
 She is now in an efficient state of  
 repair and entitled to remain as classed*

Committee's Minute 18th August 1876 Sephouse Martindale  
 Character assigned A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. in Reg. Book. **185** No. **15033** Survey held at London Date, first Survey \_\_\_\_\_ Last Survey July 31 1876  
 on the S Howarden Castle Master Matheros  
 Tonnage 1101 Built at Liverpool When built 1869 - 7 M  
 By whom built Evans Owners Rehns Mills & Co  
 Port belonging to Liverpool Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 15033 Port of Iron Classed A Years assigned. 8.75 Character in Register Book. SS Liverpool 75

Present Condition of the Decks <u>good</u>	Treenails <u>Rivets</u>	<u>good</u>	Windlass and Capstan
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	<u>"</u>	Pumps
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	<u>"</u>	Boats
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	<u>"</u>	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	<u>"</u>	Condition, how ascertained <u>sufficient</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	<u>"</u>	Sails <u>where</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	<u>"</u>	Anchors, No. of <u>3 Bars &amp; Wedge</u> <u>they</u>
Topsides <u>"</u>	Ceiling <u>"</u>	<u>"</u>	Cables <u>could</u>
Wales <u>"</u>	Rudder <u>"</u>	<u>"</u>	Hawsers and Warps <u>be seen</u>
Plank (Bottom) and Counter <u>"</u>	Copper or <u>Y.M.</u> Painted When put on <u>new</u>	<u>"</u>	Standing and Running Rigging <u>good</u>
Engine Room Skylights <u>✓</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	<u>good</u>	Cargo and Main Hatchways <u>good</u>
Coal Bunkers, Openings, Lids, &c. <u>✓</u>	Scuppers <u>good</u>	<u>good</u>	Hatches <u>good</u>

*at present bottom scraped Painted &  
 She is now in an efficient state of  
 repair and entitled to remain as classed*

Committee's Minute 18th August 1876 Sephouse Martindale  
 Character assigned A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

IRON 467 - 0524