

ANNUAL SURVEYS.

3367
26885
Reg. 24th. 76

No. in Reg. Book. **No.** 64 Survey held at London Date, first Survey 12 Aug. Last Survey 12 Aug. 18 76
on the Ship "Earl Croft" Master J. T. Kimmer
Tonnage 1312 Built at Belfast When built 1875-6 mo.
By whom built Holland Owners J. Gambles. A.S.
Port belonging to Workington Destined Voyage
If Surveyed Afloat or in Dry Dock Greens Lower Dry dock & Afloat.

Last Survey, No. 14991 Port of Iron Classed 100 A.1. Years assigned. 8-75 Character in Register Book.
Present Condition of the
Decks Good Treanails Rivets Good
Waterways — Breasthooks and Stems —
Comings — Transoms, Pointers, and Crutches —
Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
Lower Deck Beams & Fastenings — Ditto ditto at other places —
Planksheers — Keelsons —
Sheerstrakes — Clamps and Shelves —
Topsides — Ceiling —
Wales — Rudder —
Plank (Bottom) and Counter — Copper or Y.M. Cent. When put on 75.
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Bottom and keel sighted & cleaned and coated with Patent Composition and the topsides with Paint.

This Vessel is now in good and efficient condition and eligible to remain as Classed.
Committee's Minute 1st September 18 76
Character assigned 100 A.1. IRW
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) — Paid — 18 —

No. in Reg. Book. **No.** 931 Survey held at London Date, first Survey 12th Aug. Last Survey 12th Aug. 18 76
on the Ship "Europa" Master J. Campbell
Tonnage 876 Built at Newcastle When built 1862-3 mo
By whom built Palmer Owners Low - Shm. Sh. Co A.S.
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock Pontoon Victoria dock.

Last Survey, No. 14003 Port of Iron Classed 95 A.1. Years assigned. 2-75 Character in Register Book.
Present Condition of the
Decks Good Treanails Rivets Good
Waterways — Breasthooks and Stems —
Comings — Transoms, Pointers, and Crutches —
Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
Lower Deck Beams & Fastenings — Ditto ditto at other places —
Planksheers — Keelsons —
Sheerstrakes — Clamps and Shelves —
Topsides — Ceiling —
Wales — Rudder —
Plank (Bottom) and Counter — Copper or Y.M. Cent. When put on 62
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Bottom and keel examined, cleaned and coated with Paint & Tallow and the topsides with Paint.

This Vessel is now in good and efficient condition and eligible to remain as Classed.
Committee's Minute 1 September 18 76
Character assigned 95 A.1. IRW
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) — Paid — 18 —