

ANNUAL SURVEYS.

Recd 11.9.76

No. in Reg. Book. on the 414 No. S. S. Glenlyon Survey held at London Date, first Survey 9th August Last Survey 9th August 1876 Master Grange
Tonnage 1373, 2118, 2053 Built at Glasgow When built 1872 - 10 mo
By whom built Lon: & Glasgow Co Owners A. C. Gow & Co
Port belonging to Glasgow Destined Voyage China
If Surveyed Afloat or in Dry Dock Green's dry dock & afloat.

Last Survey, No. 14205 Port of London Classed + Years assigned 100 A.I. Character in Register Book. 4.75
Present Condition of the Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plating Copper or Y.M. Paint When put on now
Plank (Bottom) and Counter Good Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c.

Two new boats supplied, replacing those carried away.
She is now in good condition and eligible in my opinion to remain as classed.
The owners have been informed that this ship will be due for St. N°1 on her return from this voyage.

Committee's Minute 22nd September 1876

Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) TRW Paid 18

No. in Reg. Book. on the 108 No. S. Nelson Survey held at London Date, first Survey 4/9/76 Last Survey 8th Sept 1876 Master Leslie
Tonnage 1247, 1310, 1126 Built at Port Glasgow When built 1874 - 8 mo
By whom built Duncan & Co Owners Albion Shipping Co
Port belonging to Glasgow Destined Voyage "
If Surveyed Afloat or in Dry Dock "

Last Survey, No. 13346 Port of London Classed + Years assigned 100 A.I. Character in Register Book. 9.74
Present Condition of the Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plating Copper or Y.M. Paint When put on "
Plank (Bottom) and Counter " Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c.

Surveyed with a quantity of ballast on board.
where seen good - She is now in good condition
and eligible in my opinion to remain as classed.

Committee's Minute 22nd September 1876

Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) TRW Paid 18