

ANNUAL SURVEYS.

No. in Reg. Book. 38 No. 1473
Survey held at London Date, first Survey 7th Sept^r Last Survey 5th Sept^r 1876
on the S.S. "Naples" Master
Tonnage 2289 Built at Newcastle When built 1845 4 mo.
By whom built Palmer & Co Owners Nelson, Conklin & Co
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock Limekiln dock

Last Survey, No. 15704 Port of London Iron
Classed 100 A-1
Years assigned. 176
Character in Register Book.
Present Condition of the
Decks Treenails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers
General Observations, Opinion as to Class, &c. Cargo and Main Hatchways Hatches

This vessel has been dretted and Bottom recoated. She appears in good condition and eligible to remain as classed.

Committee's Minute 12th September 1876

Character assigned 100 A-1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. 1210
Survey held at London Date, first Survey 7th Sept^r Last Survey 8th Sept^r 1876
on the S.S. "Montgomeryshire" Master
Tonnage 1146 Built at Glasgow When built 1873 12 mo.
By whom built Douglas & Co Owners Leathin & Co
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock Fletcher dock

Last Survey, No. 13504 Port of London Iron
Classed 100 A-1
Years assigned. 1074
Character in Register Book.
Present Condition of the
Decks Treenails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers
General Observations, Opinion as to Class, &c. Cargo and Main Hatchways Hatches

Bottom cleaned and recoated.
This vessel appears in good condition and eligible to remain as classed

Committee's Minute 12th September 1876

Character assigned 100 A-1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18