

## ANNUAL SURVEYS.

No. in Reg. Book. 38 No. 1473  
Survey held at London Date, first Survey 7<sup>th</sup> Sept<sup>r</sup> Last Survey 5<sup>th</sup> Sept<sup>r</sup> 1876  
on the S.S. "Naples" Master  
Tonnage 2289 Built at Newcastle When built 1875 4 mo.  
By whom built Palmer & Co Owners Nelson, Conklin & Co  
Port belonging to London Destined Voyage  
If Surveyed Afloat or in Dry Dock Limekiln dock

Last Survey, No. 15704 Port of London Iron  
Classed 100 A-1  
Years assigned 176  
Character in Register Book.  
Present Condition of the  
Decks Treenails  
Waterways Breasthooks and Stemson  
Comings Transoms, Pointers, and Crutches  
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings  
Lower Deck Beams & Fastenings Ditto ditto at other places  
Planksheers Keelsons  
Sheerstrakes Clamps and Shelves  
Topsides Ceiling  
Wales Rudder  
Plank (Bottom) and Counter Copper or Y.M. When put on  
Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers  
General Observations, Opinion as to Class, &c. Cargo and Main Hatchways Hatches

This vessel has been dretted and Bottom recoated. She appears in good condition and eligible to remain as classed.

Committee's Minute 12<sup>th</sup> September 1876

Character assigned 100 A-1

Thos Congdon

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. 1210  
Survey held at London Date, first Survey 7<sup>th</sup> Sept<sup>r</sup> Last Survey 8<sup>th</sup> Sept<sup>r</sup> 1876  
on the S.S. "Montgomeryshire" Master  
Tonnage 1146 Built at Glasgow When built 1873 12 mo.  
By whom built Douglas & Co Owners Leathin & Co  
Port belonging to London Destined Voyage  
If Surveyed Afloat or in Dry Dock Fletcher dock

Last Survey, No. 13504 Port of London Iron  
Classed 100 A-1  
Years assigned 1074  
Character in Register Book.  
Present Condition of the  
Decks Treenails  
Waterways Breasthooks and Stemson  
Comings Transoms, Pointers, and Crutches  
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings  
Lower Deck Beams & Fastenings Ditto ditto at other places  
Planksheers Keelsons  
Sheerstrakes Clamps and Shelves  
Topsides Ceiling  
Wales Rudder  
Plank (Bottom) and Counter Copper or Y.M. When put on  
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers  
General Observations, Opinion as to Class, &c. Cargo and Main Hatchways Hatches

Bottom cleaned and recoated.  
This vessel appears in good condition and eligible to remain as classed

Committee's Minute 12<sup>th</sup> September 1876

Character assigned 100 A-1

Thos Congdon

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18