

ANNUAL SURVEYS.

25.738
Recd 26.9.76

No. in Reg. Book. **No.** 66 Survey held at London Date, first Survey 12 Sept^r Last Survey 12 Sept^r 18 76
on the "Stautilus" Master T. Hills
Tonnage 467.718.63 Built at Lunderland When built 1874 - 11th mo
By whom built Gulston Owners Gen. Steam Nav. Co
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Gridiron, Deptford Green

Last Survey, No. 13799 Port of Iron Classed + Years assigned. 90 A.1. Character in Register Book. 1.75
Present Condition of the Decks Good Iron Good
Waterways _____
Comings _____
Upper Deck Beams & Fastenings _____
Lower Deck Beams & Fastenings _____
Planksheers _____
Sheerstrakes _____
Topsides _____
Wales _____
Plating (Bottom) and Counter _____
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. _____

Lighted the bottom. Bottom cleaned and coated with Black Varnish. Upper deck caulked.
The vessel is now in good condition and eligible to remain as classed.

Committee's Minute 29 September 1876 J.W. Scullard
Character assigned 90 A.1. J.W. Scullard Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. **No.** 224 Survey held at London Date, first Survey 21 Sept^r Last Survey 22 Sept^r 18 76
on the "Benledi" Master J. Buchannan
Tonnage 100,155.7,154.3 Built at Glasgow When built 1871 - 8 mo
By whom built Banglay Owners Thomson & Co
Port belonging to Leith Destined Voyage _____
If Surveyed Afloat or in Dry Dock Millwall Dry Dock.

Last Survey, No. 15801 Port of Iron Classed 100 A.1. 11.75 Years assigned. S.S. Low: 1-75 Character in Register Book. _____
Present Condition of the Decks Good Iron Good
Waterways _____
Comings _____
Upper Deck Beams & Fastenings _____
Lower Deck Beams & Fastenings _____
Planksheers _____
Sheerstrakes _____
Topsides _____
Wales _____
Plating (Bottom) and Counter _____
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. _____

Bottom scraped and painted, rudder braces bushed.
She now appears in good condition and in my opinion eligible to remain as classed.

Committee's Minute 29 September 1876 J.W. Scullard
Character assigned 100 A.1. J.W. Scullard Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) _____ Paid _____ 18 _____

120N468-0153