

ANNUAL SURVEYS.

1703-2
 No. 1131 Survey held at Calcutta Date 5th August 1876
 on the Barque "Sunbeam" Master Clayburn
 Tonnage 1443 Built at Kircaldy When built 1857
 By whom built Owners C. W. Turner
 Port belonging to (formerly) London (now) Port Littleton Destined Voyage Canterbury N.Z.
 If Surveyed Afloat or in Dry Dock Afloat.

Last Survey, No. 1134 Port of London Iron Classed A1
 P.S. No. 3. 74

The present Condition of the

Decks	good where seen	Treenails	rivetting good where seen	Windlass and Capstan	good
Waterways	"	Breasthooks and Stemson	"	Pumps	in good order
Comings	"	Transoms, Pointers, and Crutches	"	Boats	3 all good
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	all sound
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	2 good sails
Planksheers	plating	Keelsons	"	Anchors, No. of	3 houses 2 kedges
Sheerstrakes	"	Clamps and Shelves	"	Cables	2 houses 120 fms ca 60 fms stream
Topsides	"	Ceiling	"	Hawsers and Warps	5 assorted
Wales	"	Rudder	good & well hung	Standing and Running Rigging	all good
Plank (Bottom) and Counter	"	Copper	Paint When put on May 1876		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good (decks newly caulked)

Originally a strong well built iron vessel, has been well kept up and is in my opinion fit to be retained on the register as classed.

Committee's Minute 15th Sept 1876

Character assigned

Masterwork

R. M. R.

Surveyor to Lloyd's Register of S.S. & S. Shipping.
 Port of Calcutta. The 8th August 1876
 Certificate (if required).

No. Survey held at Date 18
 on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute 18

Character assigned



© 2019

Lloyd's Register

Certificate (if required).

120N468-0236