

ANNUAL SURVEYS.

6/10/76
No. in Reg. Book. on the No. 2536 Survey held at Liverpool Date, first Survey Sep 19th Last Survey Sep 19th 1876
364 on the Bark "Glenariff" Master Herdman
Tonnage 468 Built at Dumbarton When built 1869 - 5 mo.
By whom built Mc Millan Owners W. Porter -
Port belonging to Liverpool Destined Voyage
If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 13087 Port of Glen Classed S.S. Ham No 1-74. Years assigned. 7.74. Character in Register Book. A1
Present Condition of the Decks Good Rivets. Good
Waterways " Breasthooks and Stems "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shells "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Cement When put on 69. "
Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint.
The vessel is now in a good and efficient condition, eligible in my opinion to remain as Classed.

Committee's Minute Liverpool 6th October 1876

Character assigned A1

T. Shilston.

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. in Reg. Book. on the No. 462 Survey held at Liverpool Date, first Survey Sep 18th Last Survey Sep 19th 1876
462 on the Ship "Marpesia" Master T. Storey.
Tonnage 11443 Built at P. Glasgow When built 1866 - 4 mo.
By whom built Reid Owners J. Heap & Sons
Port belonging to Liverpool Destined Voyage Melbourne.
If Surveyed Afloat or in Dry Dock Queen's Dry Dock

Last Survey, No. 15502 Port of Iron Classed S.S. Liv No 2. 74. Years assigned. 10.75. Character in Register Book. A1
Present Condition of the Decks Good Rivets Good
Waterways " Breasthooks and Stems "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shells "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Cement When put on 66 "
Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint.
The vessel is now in a good and efficient condition, eligible in my opinion to remain as Classed.

Committee's Minute Liverpool 6th October 1876

Character assigned A1

T. Shilston.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

IRON 468-0337

"*Memorij*"

©2019

Lloyd's Register
Foundation

"*Marpedun*"

25236

