

ANNUAL SURVEYS.

Reid 9.10.76

No. in Reg. Book. on the 1092 No. "Suez" Survey held at London Date, first Survey 4/10/76 Last Survey 6/10/1876
 Tonnage 1390 Built at Newcastle When built 1874-9 mo.
 By whom built Mitchell Owners Nelson, (Donkin & Co.)
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Pontoons - Victoria Dock.

Last Survey, No. 16182 Port of Iron

Classed 100 A.1
 Years assigned 4.76.

Present Condition of the

| | | | | | |
|----------------------------------|-------------|---------------------------------------|-------------------------|------------------------------|-----------------------|
| Decks | <u>good</u> | Treenails rivets | <u>good</u> | Windlass and Capstan | <u>good</u> |
| Waterways | <u>Do</u> | Breasthooks and Stemson | <u>Do</u> | Pumps | <u>Do</u> |
| Comings | <u>Do</u> | Transoms, Pointers, and Crutches | <u>Do</u> | Boats | <u>Do</u> |
| Upper Deck Beams & Fastenings | <u>Do</u> | Timbers of the Frame at the Openings | <u>Do</u> | Masts, Yards, &c. | <u>Do</u> |
| Lower Deck Beams & Fastenings | <u>Do</u> | Ditto ditto at other places | <u>not seen</u> | Condition, how ascertained | <u>from the Deck</u> |
| Planksheers | <u>Do</u> | Keelsons | <u>good where seen</u> | Sails | <u>good</u> |
| Sheerstrakes | <u>Do</u> | Clamps and Shelves | <u>good</u> | Anchors, No. of | <u>3 B. 1 S. 2 K.</u> |
| Topsides | <u>Do</u> | Ceiling | <u>good where seen.</u> | Cables | <u>good</u> |
| Wales | <u>Do</u> | Rudder | <u>good</u> | Hawsers and Warps | <u>Do</u> |
| Plating (Bottom) and Counter | <u>Do</u> | Copper or Y.M. cement | <u>When put on /74</u> | Standing and Running Rigging | <u>Do</u> |
| Engine Room Skylights | <u>good</u> | Caulking of Bottom, Deck, & Waterways | <u>good</u> | Cargo and Main Hatchways | <u>Do</u> |
| Coal Bunker, Openings, Lids, &c. | <u>good</u> | Scuppers | <u>Do</u> | Hatches | <u>Do</u> |

General Observations, Opinion as to Class, &c.

Vessel surveyed with a quantity of ballast in hold.
 Bottom of vessel cleaned, examined and painted.
 The vessel is in good and efficient condition and fit in my opinion to remain as classed.

Committee's Minute 13th October 1876

Character assigned 100 A.1

J. H. Truscott.
 Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. on the 39 No. "Lactura" Survey held at London Date, first Survey 6/10/76 Last Survey 6/10/1876
 Tonnage 1398 Built at Glasgow When built 1875-2 mo.
 By whom built Baird and Brown Owners Baird and Brown.
 Port belonging to Glasgow. Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Wigram's Dry Dock.

Last Survey, No. 14067 Port of Iron

Classed 100 A.1
 Years assigned 3.75

Present Condition of the

| | | | | | |
|-----------------------------------|-------------|---------------------------------------|-------------------------|------------------------------|-----------------------|
| Decks | <u>good</u> | Treenails rivets | <u>good</u> | Windlass and Capstan | <u>good</u> |
| Waterways | <u>Do</u> | Breasthooks and Stemson | <u>Do</u> | Pumps | <u>Do</u> |
| Comings | <u>Do</u> | Transoms, Pointers, and Crutches | <u>Do</u> | Boats | <u>Do</u> |
| Upper Deck Beams & Fastenings | <u>Do</u> | Timbers of the Frame at the Openings | <u>Do</u> | Masts, Yards, &c. | <u>Do</u> |
| Lower Deck Beams & Fastenings | <u>Do</u> | Ditto ditto at other places | <u>not seen.</u> | Condition, how ascertained | <u>from the Deck</u> |
| Planksheers | <u>Do</u> | Keelsons | <u>good where seen.</u> | Sails | <u>good</u> |
| Sheerstrakes | <u>Do</u> | Clamps and Shelves | <u>Do</u> | Anchors, No. of | <u>3 B. 1 S. 2 K.</u> |
| Topsides | <u>Do</u> | Ceiling | <u>Do</u> | Cables | <u>good</u> |
| Wales | <u>Do</u> | Rudder | <u>good</u> | Hawsers and Warps | <u>Do</u> |
| Plating (Bottom) and Counter | <u>Do</u> | Copper or Y.M. cement | <u>When put on /75</u> | Standing and Running Rigging | <u>Do</u> |
| Engine Room Skylights | <u>good</u> | Caulking of Bottom, Deck, & Waterways | <u>good</u> | Cargo and Main Hatchways | <u>good</u> |
| Coal Bunkers, Openings, Lids, &c. | <u>good</u> | Scuppers | <u>good</u> | Hatches | <u>good</u> |

General Observations, Opinion as to Class, &c.

Vessel has been surveyed with a quantity of cargo in hold.
 Bottom of vessel has been examined, cleaned and painted.
 The vessel is in good and efficient condition and fit in my opinion to remain as classed.

Committee's Minute 13th October 1876

Character assigned 100 A.1

J. H. Truscott.
 Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) _____ Paid _____ 18 _____

120N468-0418