

ANNUAL SURVEYS.

No. in Reg. Book. **No. 2527⁵** Survey held at **Liverpool** Date, first Survey **6 Oct^r** Last Survey **16 Oct^r** 18**76**
 on the **Bk "Coronilla"** Master **C. Mossop**
 Tonnage **524** Built at **Liverpool** When built **1865-1 mo**
 By whom built **Evam** Owners **J. Gambles**
 Port belonging to **Liverpool** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Clarence G. Brck**

Last Survey, No. **11659** Port of **Lion** Classed ***A1**
 Present Condition of the Decks **gnd** **Freemile Parits** **gnd**
 Waterways **"** Breasthooks and Stemson **"**
 Comings **"** Transoms, Pointers, and Crutches **"**
 Upper Deck Beams & Fastenings **"** ~~Timbers of the Frame at the Openings~~ **"**
 Lower Deck Beams & Fastenings **"** ~~Ditto ditto at other places~~ **"**
 Planksheers **"** Keelsons **"**
 Sheerstrakes **"** Clamps and Shelves **"**
 Topsides **"** Ceiling **"**
 Wales **"** Rudder **"**
 Plank (Bottom) and Counter **"** ~~Copper or Y.M. Cement~~ When put on **65**
 Engine Room Skylights **-** Coal Bunker, Openings, Lids, &c. **-** Scuppers **gnd** Cargo and Main Hatchways **gnd** Hatches **gnd**
 General Observations, Opinion as to Class, &c.

This vessel has now been docked & the bottom cleaned & painted, & being in gnd condition is eligible in my opinion to remain as classed

Committee's Minute **Liverpool Nov^r 10 - 1876.**
 Character assigned ***A1**

Geo. T. Cooper
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **18**

No. in Reg. Book. **No. 54** Survey held at **Liverpool** Date, first Survey **17 Oct** Last Survey **17 Oct** 18**76**
 on the **Bk "Lady Bird"** Master **Bevan**
 Tonnage **498** Built at **Liverpool** When built **1866-3 mo**
 By whom built **429** **Royden** Owners **A. B. Geddes**
 Port belonging to **Liverpool** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Clarence G. Brck**


Last Survey, No. **13489** Port of **Lion** Classed ***A1**
 Present Condition of the Decks **gnd** **Freemile Parits** **gnd**
 Waterways **"** Breasthooks and Stemson **"**
 Comings **"** Transoms, Pointers, and Crutches **"**
 Upper Deck Beams & Fastenings **"** ~~Timbers of the Frame at the Openings~~ **"**
 Lower Deck Beams & Fastenings **"** ~~Ditto ditto at other places~~ **"**
 Planksheers **"** Keelsons **"**
 Sheerstrakes **"** Clamps and Shelves **"**
 Topsides **"** Ceiling **"**
 Wales **"** Rudder **"**
 Plank (Bottom) and Counter **"** ~~Copper or Y.M. Cement~~ When put on **66**
 Engine Room Skylights **-** Coal Bunkers, Openings, Lids, &c. **-** Scuppers **gnd** Cargo and Main Hatchways **gnd** Hatches **gnd**
 General Observations, Opinion as to Class, &c.

This vessel has now been docked, the bottom cleaned & painted & being in gnd condition is eligible in my opinion to remain as classed

Committee's Minute **Liverpool Nov^r 10 - 1876.**
 Character assigned ***A1**

Geo. T. Cooper
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **18**

"
Barnwell
" Lady David
"



© 2019

Lloyd's Register
Foundation