

# ANNUAL SURVEYS.

No. 128  
1083

Survey held at

Dublin

Date

7 October

1876

on the *Hon Bague Beigomart*

Master

Tonnage 600

Built at

Port Glasgow

When built

1866: 10<sup>th</sup> Mo

By whom built

Reid

Owners

Messrs Brownrig & Co

Port belonging to

Liverpool

Destined Voyage

If Surveyed Afloat or in Dry Dock

In dry Dock

Last Survey, No.

15209

Port of

Liver

Classed \*A1. 11.75

S.S. No 2.75

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Paint

When put on

now

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Placed on blocks in dry dock, the keel & bottom examined and found in good condition. The bottom has been cleaned and coated with two coats of paint and one of white lead and tallow. I consider this vessel to be now in a good & efficient state of repair and "fit for the safe conveyance of dry & perishable cargoes to & from all parts of the world" and in my opinion eligible to remain as classed in the Register Book.

Committee's Minute

7<sup>th</sup> November 1876

Character assigned

Surveyor for L. 1. 1. 0. A. P. M. W. H. M. P.

DBW

Certificate (if required)

No.

Survey held at

Date

18

on the

Master

Tonnage

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute

18

Character assigned



© 2019

Lloyd's Register Foundation

Certificate (if required).

18468-0488