

ANNUAL SURVEYS.

25787

No. in Reg. Book. 244 No. 1200 Survey held at London Date, first Survey 30th Oct. Last Survey 2nd Nov. Recd. 24.11.76
 on the Ship "Carnarvon Castle" Master Robinson
 Tonnage 1200 Built at Glasgow When built 1867 - 6 mo
 By whom built Barclay Owners S. Currie & Co.
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Canal by lock & afloat.

Last Survey, No. 15116 Port of Iron Classed S.S. Lon No 2-75 Character in Register Book. A.1.
 Present Condition of the
 Decks Good Treenails Rivets good S.S. Lon No 2-75. 8-75.
 Waterways Good Breasthooks and Stenson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Cent. When put on 1867
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom and keel examined cleaned and coated with Patent Composition and the topsides with Paint.

This vessel is now in good and efficient condition and eligible to remain as classed.
 Committee's Minute 28th November 1876
 Character assigned A.1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. 1302 No. 1594 Survey held at London Date, first Survey 31st Oct. Last Survey 23rd Nov. 1876
 on the Ship "Mysore" Master W. Rome
 Tonnage 1651 Built at Birkenhead When built 1869 - 3 mo
 By whom built Chorner Owners W. Rome
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Beford Green by lock.

Last Survey, No. 15620 Port of Iron Classed S.S. No. 1-73 Character in Register Book. A.1.
 Present Condition of the
 Decks Good Treenails Rivets good S.S. No. 1-73. 12-75.
 Waterways Good Breasthooks and Stenson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Cent. When put on 1869
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom and keel examined cleaned and coated with Patent Composition and the topsides with Paint.

This vessel is now in good and efficient condition and in my opinion eligible to remain as classed.
 Committee's Minute 28th November 1876
 Character assigned A.1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18