

ANNUAL SURVEYS.

24/11/76

Rec 25/11/76

383

No. in Reg. Book. **290** No. **25290** Survey held at **Liverpool** Date, first Survey **17 Oct-2** Last Survey **17 Oct-1876**
 on the **BM "Sarah & Emma"** Master **Ritchard**
 Tonnage **1097** Built at **Liverpool** When built **1860-9 mo.**
 By whom built **Vernon** Owners **Hughes H.**
 Port belonging to **Liverpool** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Clarence G. OH**

Last Survey, No. 11896 Port of Iron		Classed	Years assigned.	Character in Register Book
Present Condition of the Decks gn				*A1
Waterways gn	Parts gn			10-73
Comings gn	Breasthooks and Stemson gn			S.S. Li. No 3-73
Upper Deck Beams & Fastenings gn	Transoms, Pointers, and Crutches gn			Windlass and Capstan gn
Lower Deck Beams & Fastenings gn	Timbers of the Frame at the Openings gn			Pumps gn
Planksheers gn	Ditto ditto at other places			Boats gn
Sheerstrakes gn	Keelsons gn			Masts, Yards, &c. gn
Topsides gn	Clamps and Shelves gn			Condition, how ascertained inspection
Wales gn	Ceiling gn			Sails complete
Plank (Bottom) and Counter gn	Rudder gn			Anchors, No. of 3/B. 15. 2H.
Engine Room Skylights gn	Copper on V.M. Cement When put on 60.			Cables complete
Coal Bunker, Openings, Lids, &c. gn	Caulking of Bottom, Deck, & Waterways gn			Hawsers and Warps gn
Scuppers gn				Standing and Running Rigging gn
Cargo and Main Hatchways gn				Hatches gn

General Observations, Opinion as to Class, &c.
This vessel has now been docked, the bottom cleaned & painted & being in good condition is eligible in my opinion to remain as classed

Committee's Minute **Liverpool Novth 24 1876**
 Character assigned ***A1**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. " Survey held at **Liverpool** Date, first Survey **10 Oct-** Last Survey **20th Oct-1876**
 on the **BM "Belle of Benin"** Master **Elliott**
 Tonnage **205** Built at **Sunderland** When built **1875-5 mo.**
 By whom built **Pulston** Owners **J. Harrison H.**
 Port belonging to **Liverpool** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Canning G. OH**

Last Survey, No. 14496 Port of Iron		Classed	Years assigned.	Character in Register Book
Present Condition of the Decks gn				100 A1
Waterways gn	Parts gn			5-75
Comings gn	Breasthooks and Stemson gn			Windlass and Capstan gn
Upper Deck Beams & Fastenings gn	Transoms, Pointers, and Crutches gn			Pumps gn
Lower Deck Beams & Fastenings gn	Timbers of the Frame at the Openings gn			Boats gn
Planksheers gn	Ditto ditto at other places			Masts, Yards, &c. gn
Sheerstrakes gn	Keelsons gn			Condition, how ascertained inspection
Topsides gn	Clamps and Shelves gn			Sails complete
Wales gn	Ceiling gn			Anchors, No. of 3/B. 15. 2H.
Plank (Bottom) and Counter gn	Rudder gn			Cables complete
Engine Room Skylights gn	Copper on V.M. Cement When put on 75			Hawsers and Warps gn
Coal Bunkers, Openings, Lids, &c. gn	Caulking of Bottom, Deck, & Waterways gn			Standing and Running Rigging gn
Scuppers gn				Hatches gn
Cargo and Main Hatchways gn				

General Observations, Opinion as to Class, &c.
This vessel has now been docked, the bottom cleaned and repainted & being in good condition is eligible in my opinion to remain as classed

Committee's Minute **Liverpool Novth 24 1876.**
 Character assigned **100 A1**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

"Sarah Comina"

"Bell of Benini"
25290



© 2019

Lloyd's Register
Foundation