

ANNUAL SURVEYS.

24/1/76
No. 25280 Survey held at Liverpool Date, first Survey 17 Oct-2 Last Survey 17 Oct-2 1876
Reg. Book. on the BM "Sarah & Emma" Master Ritchard
Tonnage 1027 Built at Liverpool When built 1860-9 mo.
By whom built Vernon Owners Hughes H.
Port belonging to Liverpool Destined Voyage
If Surveyed Afloat or in Dry Dock Clarence G. OH

Last Survey, No. 11896 Port of Iron Classed 10-43 Character in Register Book *A1
Present Condition of the Decks good Parts fin
Breasthooks and Stemson fin
Transoms, Pointers, and Crutches fin
Timbers of the Frame at the Openings fin
Ditto ditto at other places fin
Keelsons fin
Clamps and Shelves fin
Ceiling fin
Rudder fin
Copper on V.M. Cement When put on 60
Caulking of Bottom, Deck, & Waterways fin
Windlass and Capstan fin
Pumps fin
Boats fin
Masts, Yards, &c. fin
Condition, how ascertained inspection
Sails complete
Anchors, No. of 3/B. 15. 2H.
Cables complete
Hawsers and Warps fin
Standing and Running Rigging fin
Hatches fin
Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers fin Cargo and Main Hatchways fin
General Observations, Opinion as to Class, &c.

This vessel has now been docked, the bottom cleaned & painted & being in good condition is eligible in my opinion to remain as classed

Committee's Minute Liverpool Nov-24th 1876
Character assigned *A1

Geo. I. Cooper
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. " Survey held at Liverpool Date, first Survey 10 Oct- Last Survey 20th Oct- 1876
Reg. Book. on the BM "Belle of Benin" Master Elliott
Tonnage 205 Built at Sunderland When built 1875-5 mo.
By whom built Puleston Owners J. Harrison H.
Port belonging to Liverpool Destined Voyage
If Surveyed Afloat or in Dry Dock Canning G. OH

Last Survey, No. 14496 Port of Iron Classed 100 A1 Character in Register Book 5-75
Present Condition of the Decks fin Parts fin
Breasthooks and Stemson fin
Transoms, Pointers, and Crutches fin
Timbers of the Frame at the Openings fin
Ditto ditto at other places fin
Keelsons fin
Clamps and Shelves fin
Ceiling fin
Rudder fin
Copper on V.M. Cement When put on 75
Caulking of Bottom, Deck, & Waterways fin
Windlass and Capstan fin
Pumps fin
Boats fin
Masts, Yards, &c. fin
Condition, how ascertained inspection
Sails complete
Anchors, No. of 3/B. 15. 2H.
Cables complete
Hawsers and Warps fin
Standing and Running Rigging fin
Hatches fin
Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers fin Cargo and Main Hatchways fin
General Observations, Opinion as to Class, &c.

This vessel has now been docked, the bottom cleaned and renovated & being in good condition is eligible, in my opinion, to remain as classed

Committee's Minute Liverpool Nov-24th 1876.
Character assigned 100 A1

Geo. I. Cooper
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

"Sarah Emma"
"Bell of Benin"
25290



© 2019

Lloyd's Register
Foundation