

ANNUAL SURVEYS.

No. in Reg. Book. on the **No.** 59 Survey held at London Date, first Survey 24th Nov Last Survey 28th Nov 1876
S. Bannockburn Master J. Young
 Tonnage 1675, 1769, 1610 Built at Greenock When built 1875 - 4th mo.
 By whom built Steel Owners R. Shankland
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Canal Dry Dock B.

Last Survey, No. 14279 Port of Iron Classed + Years assigned. 100 A.I. Character in Register Book. 4-75
 Present Condition of the Decks Good
 Waterways _____ Treennails Rivets Good
 Comings _____ Breasthooks and Stemson _____
 Upper Deck Beams & Fastenings _____ Transoms, Pointers, and Crutches _____
 Lower Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Planksheers _____ Ditto ditto at other places _____
 Sheerstrakes _____ Keelsons _____
 Topsides _____ Clamps and Shelves _____
 Wakes _____ Ceiling _____
 Plating _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. Paint. When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

Surveyed with a quantity of ballast on board.
Vessel placed in dry dock, bottom scraped and painted.
She appears in good condition and eligible in my opinion to remain as classed.

Committee's Minute 12th December 1876 J.W. Scullard
 Character assigned 100 A.I. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. on the **No.** XXI 679 Survey held at London Date, first Survey 21st Nov Last Survey 22nd Nov 1876
S. "British Monarch" Master H. B. Banks
 Tonnage 1262 Built at Birkenhead When built 1865 - 4th mo.
 By whom built Clower Owners British Ship Owners Co
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Canal Dry Dock C.

Last Survey, No. 15922 Port of Iron Classed + Years assigned. *A.I. Character in Register Book. 2-76
 Present Condition of the Decks Good
 Waterways _____ Treennails Rivets Good
 Comings _____ Breasthooks and Stemson _____
 Upper Deck Beams & Fastenings _____ Transoms, Pointers, and Crutches _____
 Lower Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Planksheers _____ Ditto ditto at other places _____
 Sheerstrakes _____ Keelsons _____
 Topsides _____ Clamps and Shelves _____
 Wakes _____ Ceiling _____
 Plating _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. Paint. When put on now
 Caulking of Bottom, Deck, & Waterways _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

Surveyed with ballast and a portion of the outward cargo on board.
Vessel placed in dry dock, bottom scraped and painted.
Head rails renewed.
She now appears in good condition and eligible in my opinion to remain as classed.

Committee's Minute 12th December 1876 J.W. Scullard
 Character assigned *A.I. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____