

REPORT of SURVEY for REPAIRS, &c.

Recd 13. 12. 76

No. in Reg. Book. **No.** *50* on the *S. S. Hankow* Survey held at *London* Date, first Survey *27th Nov^r* Last Survey *8 Dec^r* 18*76*

Master *Springton*

TONNAGE under Tonnage Deck *3153*
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage *3594*
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St^rmer, cut on Bm. *2339*

Built at *Newcastle* When built *1873*
 Owners *Watts & Miller* Port belonging to *London*
 Residence
 By whom built *Mitchell* Destined Voyage
 If Surveyed Afloat or in Dry Dock *afloat S. W. I. Dock*

Length of Poop *ft.* Ditto, Forecastle *ft.* Ditto, Raised Quarter Deck *ft.* Years assigned. *100.41*
 Character in Register Book. *8.76*

Last Survey, No. **16919* Port *London* Classed

REPAIRS, OR EXAMINATION AS PER RULE

Four side lights, each 8 in diameter. Lane beam cut in the Sheerstrake on Star^d side, and three ditto on the Port side, from the Fore Hatchway forward. And as compensation for cutting those lights, a Clamp plate 16 x 5 has been introduced there and connected to frames. The length of Clamp plate being about 58 feet.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the opening

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

This vessel appears in good condition and eligible to remain as classed.

The Amount of Entry Fee ... £ ... received by me, *18/12/76*

Special ... £2 : 2 : 15 Dec^r 1876

Certificate (if required) ... £ : 5 :

(Travelling Expenses, if any, £ ...)

Committee's Minute *15th December* 18*76*

Character assigned *100 A 1*

Wm C. Dacey
 Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON469-0274