

# ANNUAL SURVEYS.

No. in Reg. Book. 20 No. 16279 Survey held at London Date, first Survey 23<sup>rd</sup> Nov Last Survey 29<sup>th</sup> Nov 1876  
 Tonnage 518, 762, 712 Built at Newcastle When built 1865 — 8<sup>th</sup> mo  
 By whom built Palmer Owners S. Clark & Co  
 Port belonging to London Destined Voyage —  
 If Surveyed Afloat or in Dry Dock Commercial dry dock

Last Survey, No. 16279 Port of Iron Classed — Years assigned. — Character in Register Book. A 1 4.76  
 Present Condition of the Decks Good Iron Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
Plating Bottom and Counter " Copper or V.M. Paint When put on now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers " Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Ship placed in dry dock, bottom scraped and painted. Raised quarter deck caulked.  
Is now in good condition and fit in my opinion to remain as classed.

Committee's Minute 19<sup>th</sup> December 1876 J.W. Seallard  
 Character assigned A 1 J.W. Seallard Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid — 18 —

No. in Reg. Book. 440 No. 16764 Survey held at London Date, first Survey 6<sup>th</sup> Dec Last Survey 8<sup>th</sup> Dec 1876  
 Tonnage 1410 Built at Glasgow When built 1870 — 9<sup>th</sup> mo  
 By whom built Lon. & Glasgow S. Building Co Owners Mercantile S. Ship Co  
 Port belonging to London Destined Voyage —  
 If Surveyed Afloat or in Dry Dock Millwall dock - dry dock

Last Survey, No. 16764 Port of Iron Classed — Years assigned. — Character in Register Book. 80 A. 1.27  
 Present Condition of the Decks Good Iron Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
Plating Bottom and Counter " Copper or V.M. Paint When put on now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers " Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Ship placed in dry dock, bottom cleaned and painted.  
She is in good condition, and fit in my opinion to remain as classed.

Committee's Minute 19<sup>th</sup> December 1876 J.W. Seallard  
 Character assigned 80 A 1 J.W. Seallard Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid — 18 —

180469-0283