

ANNUAL SURVEYS.

Recd 1.12.76

No. in Reg. Book. **806** No. **11501** Survey held at London Date, first Survey — Last Survey Nov 29 1876
 on the SS Ludworth Master —
 Tonnage 304 Built at Glasgow When built 1866 SM
 By whom built Mingate Owners Original Hopl Col Co
 Port belonging to Hartlepool London Destined Voyage —
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 11501 Port of Liverpool
 Present Condition of the Decks Good Greenails Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. — When put on —
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. —

Years assigned. 1 Character in Register Book. 6.76
 Classed B1 S.S. No. 2.74

At present a small chain having got entangled on the screw shaft made the Propeller slack, has now been made firm & tight. She is in an efficient state of repair and entitled to remain as classed.

Committee's Minute 12th December 1876 Senhouse Martindale
 Character assigned B1 IPW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid 18

No. **155** Survey held at London Date, first Survey Nov 13 Last Survey Nov 15 1876
 on the S Fernglan Master Fraser
 Tonnage 818 Built at Sunderland When built 1874 10 mo.
 By whom built Blumer Owners R B Porrett
 Port belonging to Sunderland Destined Voyage —
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 13347 Port of Liverpool
 Present Condition of the Decks Good Greenails Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Painted When put on Nov
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom scraped & coated as previous

Years assigned. 100A1 Character in Register Book. 12.75
 Classed 100A1

She is now in an efficient state of repair and entitled to remain as classed.

Committee's Minute 12th December 1876 Senhouse Martindale
 Character assigned 100A1 IPW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid 18