

ANNUAL SURVEYS.

No. in Reg. Book. 53 No. 3729 Survey held at West Hartlepool Date, first Survey 7 Dec Last Survey 7 Dec 1876
 on the Screw S.S. "Madras" Master Green
 Tonnage 1679 Built at Stockton When built 1874 - 7mo
 By whom built Pearse Owners R. A. Learoyd
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 16652 Port of Iron Classed 90 A1 Character in Register Book 7/76
 Present Condition of the Decks Good Treenails Good
 Waterways Good Breasthooks and Stems Good
 Comings " Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings " Ditto ditto at other places Good
 Plank sheers _____ Keelsons Good
 Sheerstrakes Good Clamps and Shelves _____
 Topsides " Ceiling Good
 Wales " Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. _____ When put on _____
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom cleaned & painted & boards with paint
Is now in a good & efficient state fit for the conveyance of dry & perishable goods to & from all parts of the world & may in my opinion remain as now classed 90 A1

Committee's Minute 19th December 1876 Character assigned 90 A1
 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) _____ Paid _____ 18____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in Reg. Book. on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stems _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Plank sheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____ Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) _____ Paid _____ 18____



180469-0300