

ANNUAL SURVEYS.

17499

No. in Reg. Book **25321** Survey held at Liverpool Date, first Survey Nov 29th Last Survey Nov 29th 1876
 on the Ship "Erysomene" Master J. Browning
 Tonnage 1778 Built at Liverpool When built 1873 - 11 mo.
 By whom built Potter Owners A. Fernie & Co.
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 14198 Port of Liverpool Classed 100 AL Years assigned 2.75 Character in Register Book 100 AL

Present Condition of the Decks	Good	Timber	Rivets.	Good	Windlass and Capstan	Good
Waterways	✓	Breasthooks and Stemson			Pumps	✓
Comings	✓	Transoms, Pointers, and Crutches			Boats	✓
Upper Deck Beams & Fastenings	✓	Timbers of the Frame at the Openings	✓		Masts, Yards, &c.	✓
Lower Deck Beams & Fastenings	✓	Ditto ditto at other places	✓		Condition, how ascertained from on board	✓
Planksheers	✓	Keelsons	✓		Sails	Good
Sheerstrakes	✓	Clamps and Shells	✓		Anchors, No. of <u>3B - 1S - 2K</u>	✓
Topsides	✓	Ceiling	✓		Cables <u>part seen</u>	Good
Wales	✓	Rudder	✓		Hawsers and Warps	and
Plank (Bottom) and Counter	✓	Copper or Y.M. Cement When put on <u>73</u>	✓		Standing and Running Rigging	Sufficient
Engine Room Skylights	✓	Caulking of Bottom, Deck, & Waterways	Good		Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	✓	Scuppers	Good		Hatches	Good

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint.
This vessel being in good and efficient condition
is in my opinion, eligible to remain as Classed -

Committee's Minute Liverpool Dec^r 27th 1876. Character assigned 100 AL
J. Shilston.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book **185** Survey held at Liverpool Date, first Survey Dec 9th Last Survey Dec 9th 1876
 on the Ship "Victoria Nyanga" Master Lodge
 Tonnage 1022 Built at Belfast When built 1863 - 8 mo.
 By whom built Harland Owners G. A. Fletcher.
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 15337 Port of Liverpool Classed S.S. Liv No 3.74 Years assigned 11.75 Character in Register Book AL

Present Condition of the Decks	Good	Timber	Rivets.	Good	Windlass and Capstan	Good
Waterways	✓	Breasthooks and Stemson			Pumps	✓
Comings	✓	Transoms, Pointers, and Crutches			Boats	✓
Upper Deck Beams & Fastenings	✓	Timbers of the Frame at the Openings	✓		Masts, Yards, &c.	✓
Lower Deck Beams & Fastenings	✓	Ditto ditto at other places	✓		Condition, how ascertained from on board	✓
Planksheers	✓	Keelsons	✓		Sails	Good
Sheerstrakes	✓	Clamps and Shells	✓		Anchors, No. of <u>3B - 1S - 2K</u>	✓
Topsides	✓	Ceiling	✓		Cables <u>part seen</u>	Good
Wales	✓	Rudder	✓		Hawsers and Warps	and
Plank (Bottom) and Counter	✓	Copper or Y.M. Cement When put on <u>73</u>	✓		Standing and Running Rigging	Sufficient
Engine Room Skylights	✓	Caulking of Bottom, Deck, & Waterways	Good		Cargo and Main Hatchways	Good
Coal Bunkers, Openings, Lids, &c.	✓	Scuppers	Good		Hatches	Good

General Observations, Opinion as to Class, &c.
Bottom sighted cleaned and coated with paint.
This vessel being in good and efficient condition
is in my opinion, eligible to remain as Classed.

Committee's Minute Liverpool Dec^r 27th 1876. Character assigned 100 AL
J. Shilston.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

"Chrysomere
25321



© 2019

Lloyd's Register
Foundation