

ANNUAL SURVEYS.

No. in Reg. Book. on the 7th Suppl. No. 874 Survey held at London Date, first Survey 30th Nov Last Survey 30th Nov 1876
S. S. "Hollamshire" Master Sanderson
 Tonnage 1358 Built at Hartlepool When built 1876. 6 mo
 By whom built Withy Owners Steel Young & Co.
 Port belonging to W. Hartlepool Destined Voyage
 If Surveyed Afloat or in Dry Dock Blackwall Point by 15

Last Survey, No. 16752 Port of Iron Classed 100 A.1.
 Present Condition of the
 Decks good Treennails Rivets good
 Waterways — Breasthooks and Stems —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shelves —
 Topsides — Ceiling —
 Wales — Rudder —
 Plate — Copper or Y.M. Cent. When put on 1876
 Plank (Bottom) and Counter — Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Bottom cleaned and coated with Patent composition,

This Vessel is now in good and efficient condition, and eligible to remain as Classed.

Committee's Minute 22nd December 1876 Character assigned 100 A.1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18

No. in Reg. Book. on the 94th No. 1930 Survey held at London Date, first Survey 14th Dec Last Survey 14th Dec 1876
S. S. "Merkara" Master J. Ballantine
 Tonnage 2971 Built at Sumbarton When built 1875. 7 mo
 By whom built Benny Owners S. Macneil & P. Benny.
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Thames Limited by Lock

Last Survey, No. 14950 Port of Iron Classed 100 A.1.
 Present Condition of the
 Decks good Treennails Rivets good
 Waterways — Breasthooks and Stems —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shelves —
 Topsides — Ceiling —
 Wales — Rudder —
 Plate — Copper or Y.M. Cent. When put on 1875
 Plank (Bottom) and Counter — Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Bottom and keel sighted, cleaned and coated with Patent Composition.

This Vessel is now in good and efficient condition and eligible to remain as Classed.

Committee's Minute 22nd December 1876 Character assigned 100 A.1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18

150N469 0376