

ANNUAL SURVEYS.

No. in Reg. Book. **No. 2450** Survey held at **Swansea** Date, first Survey **7th Dec^r** Last Survey **12th Dec^r** 18**76**
 on the **Iron Barge "Mary Jose"** Master **Trevena**
 Tonnage **625** Built at **Cumbarton** When built **1876** 1st Mo
 By whom built **Birrell** Owners **J Jose & Co**
 Port belonging to **Falmouth** Destined Voyage **Tocopila**
 If Surveyed Afloat & in Dry Dock **Richardsons Dry Dock**

Last Survey, No. **15961** Port of **Lion**

Present Condition of the

Decks	good	Treenails	Rivets	good	Classed	Years assigned.	Character in Register Book.
Waterways	"	Breasthooks and Stemson	"	"			100 A1
Comings	"	Transoms, Pointers, and Crutches	"	"			3.76
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"			
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"			
Planksheers	"	Keelsons	"	"			
Sheerstrakes	"	Clamps and Shelves	"	"			
Topsides	"	Ceiling	"	"			
Wales	"	Rudder	"	"			
Plank (Bottom) and Counter	"	Copper on Y.M. Paint When put on Now					
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	good				
Coal Bunker, Openings, Lids, &c.		Scuppers	"				
General Observations, Opinion as to Class, &c.	This vessel has now been cleared and painted from the keel to gunwales is in good condition and entitled to remain as classed.						

Committee's Minute **22nd December** 18**76**

Character assigned **100 A1** **DRW**

Thos Ashton

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) **24** Paid **20th Dec^r** 18**76**

No. in Reg. Book. **No.** Survey held at **Survey held at** Date, first Survey **Date, first Survey** Last Survey **Last Survey** 18**18**
 on the **on the** Master **Master**
 Tonnage **Tonnage** Built at **Built at** When built **When built**
 By whom built **By whom built** Owners **Owners**
 Port belonging to **Port belonging to** Destined Voyage **Destined Voyage**
 If Surveyed Afloat or in Dry Dock **If Surveyed Afloat or in Dry Dock**

Last Survey, No. **Last Survey, No.** Port of **Port of**

Classed **Classed** Years assigned. **Years assigned.** Character in Register Book. **Character in Register Book.**

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors, No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper or Y.M. When put on	Standing and Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Cargo and Main Hatchways
Coal Bunkers, Openings, Lids, &c.	Scuppers	Hatches
General Observations, Opinion as to Class, &c.		

Committee's Minute **18**

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) **24** Paid **20th Dec^r** 18**76**

ANNUAL SURVEYS
No 2450 Swansea



© 2019

Lloyd's Register
Foundation