

ANNUAL SURVEYS.

No. in Reg. Book. on the **No.** 31 Survey held at London Date, first Survey 8th Decr Last Survey 8th Decr 1876
S. "British Enterprise" Master Greig
 Tonnage 1640 Built at Stockton When built 1876 - 10 mo
 By whom built Richardson Owners British ship owners' Co
 Port belonging to Liverpool Destined Voyage —
 If Surveyed Afloat or in Dry Dock Canal dry dock

Last Survey, No. 17331 Port of Iron Classed 100 A. 1. 11.76
 Present Condition of the Decks Good
 Waterways " Treennails Rivets Good
 Comings " Breasthooks and Stemson "
 Upper Deck Beams & Fastenings " Transoms, Pointers, and Crutches "
 Lower Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Planksheers " Ditto ditto at other places "
 Sheerstrakes " Keelsons "
 Topsides " Clamps and Shelves "
 Wales " Ceiling "
 Plating " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers " Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
Surveyed with railway chairs on board.
Bottom cleaned and painted - She is in good condition
and fit to remain as classed.

Committee's Minute 5th January 1877 J. W. Scullard
 Character assigned 100 A. 1. 11.76 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18 —

No. in Reg. Book. on the **No.** 217 Survey held at London Date, first Survey 13th Decr Last Survey 13th Decr 1876
S. "Western Monarch" Master J. Watson
 Tonnage 1315 Built at Barrow When built 1875 - 8 mo
 By whom built Barrow Co Owners Rt Exchange Shipping Co
 Port belonging to London Destined Voyage —
 If Surveyed Afloat or in Dry Dock Canal dry dock

Last Survey, No. 15469 Port of Iron Classed 100 A. 1. 11.75
 Present Condition of the Decks Good
 Waterways " Treennails Rivets Good
 Comings " Breasthooks and Stemson "
 Upper Deck Beams & Fastenings " Transoms, Pointers, and Crutches "
 Lower Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Planksheers " Ditto ditto at other places "
 Sheerstrakes " Keelsons "
 Topsides " Clamps and Shelves "
 Wales " Ceiling "
 Plating " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
Surveyed with ballast on board - Bottom scraped
and painted. The vessel appeared in good condition
and fit in my opinion to remain as classed.

Committee's Minute 5th January 1877 J. W. Scullard
 Character assigned 100 A. 1. 11.75 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18 —