

ANNUAL SURVEYS.

No. in Reg. Book. **148** No. **25333** Survey held at **Liverpool** Date, first Survey **Dec 13th** Last Survey **Dec 18th** 1876
 on the Ship **"Wave Queen"** Master **G. Anderson**
 Tonnage **853** Built at **Glasgow** When built **1861 - 10 mo**
 By whom built **Stephen** Owners **Park Bros.**
 Port belonging to **London** Destined Voyage **Sydney**
 If Surveyed Afloat or in Dry Dock **Brunswick Dry Dock.**

Last Survey, No. **14240** Port of **Liverpool** Classed **SS Lon No 3-75** Years assigned. **4-75** Character in Register Book. ***A1**
 Present Condition of the Decks **Good** **Freemasts Rivets Good**
 Waterways **Good** **Breasthooks and Stemson**
 Comings **Good** **Transoms, Pointers, and Crutches**
 Upper Deck Beams & Fastenings **Good** **Timbers of the Frame at the Openings**
 Lower Deck Beams & Fastenings **Good** **Ditto ditto at other places**
 Planksheers **Good** **Keelsons**
 Sheerstrakes **Good** **Clamps and Shelves**
 Topsides **Good** **Ceiling**
 Wales **Good** **Rudder**
 Plank (Bottom) and Counter **Good** **Copper or Y.M. Paint When put on Now**
 Engine Room Skylights **✓** Coal Bunker, Openings, Lids, &c. **✓** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint, rudder hangings repaired, and put into a thoroughly efficient state. This vessel being in a good condition, is eligible in my opinion to remain as Classed.

Committee's Minute **Liverpool Jan 9th 1877** **J. Shilston.**
 Character assigned ***A1** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **✓** Paid **18**

No. **11** Survey held at **Liverpool** Date, first Survey **Dec 21st** Last Survey **Dec 21st** 1876
 No. in Reg. Book. **985** on the Ship **"Merwanjee Framjee"** Master **N. P. Bidwell**
 Tonnage **1679** Built at **Glasgow** When built **1863 - 5 mo.**
 By whom built **Reid** Owners **Johnston & Co**
 Port belonging to **Liverpool** Destined Voyage **Melbourne**
 If Surveyed Afloat or in Dry Dock **Queens Dry Dock.**

Last Survey, No. **16420** Port of **Liverpool** Classed **SS Lon No 3-75** Years assigned. **4-76** Character in Register Book. ***A1**
 Present Condition of the Decks **Good** **Freemasts Rivets Good**
 Waterways **Good** **Breasthooks and Stemson**
 Comings **Good** **Transoms, Pointers, and Crutches**
 Upper Deck Beams & Fastenings **Good** **Timbers of the Frame at the Openings**
 Lower Deck Beams & Fastenings **Good** **Ditto ditto at other places**
 Planksheers **Good** **Keelsons**
 Sheerstrakes **Good** **Clamps and Shelves**
 Topsides **Good** **Ceiling**
 Wales **Good** **Rudder**
 Plank (Bottom) and Counter **Good** **Copper or Y.M. Cement When put on 1863.**
 Engine Room Skylights **✓** Coal Bunkers, Openings, Lids, &c. **✓** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with McInnes composition, and the vessel now being in a good and efficient condition, she is eligible in my opinion to remain as Classed.

Committee's Minute **Liverpool Jan 9th 1877** **J. Shilston.**
 Character assigned ***A1** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **✓** Paid **18**

Wave Queen

Merwanger's Name
2533



© 2019

Lloyd's Register
Foundation