

17620 ANNUAL SURVEYS.

Rec 15/1/17

No. 63 Survey held at Calcutta Date 2nd December 1876.
 on the "Sandora" Master Storey
 Tonnage 1156 Built at Glasgow When built 1864
 By whom built Cornell Owners Sandbach & Co
 Port belonging to Liverpool Destined Voyage Demerara
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. <u>13346</u>	Port of <u>Iron Calcutta</u>	Classed <u>#A1</u>	
The present Condition of the		S.I. No. 2-74 ^{11.75}	
Decks <u>good where seen</u>	Treenails <u>rivetting good where seen</u>	Windlass and Capstan <u>good</u>	
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>in good condition</u>	
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>6 all in good order</u>	
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>sound</u>	
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Sails <u>2 suits</u>	
Plank sheers <u>plating</u>	Keelsons <u>"</u>	Anchors, No. of <u>3 Bowers, 1 Stream, 2 Keags</u>	
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>2 bowers 150 fms @ 75 fms stream</u>	
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>6 assorted sizes</u>	
Wales <u>"</u>	Rudder <u>good & well hung</u>	Standing and Running Rigging <u>all sound</u>	
Plank (Bottom) and Counter <u>"</u>	Copper <u>Paint</u> When put on <u>July 1876</u>		
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways <u>decks and waterways need</u>	
A strong well built iron vessel, has been carefully kept and is in my opinion fit to be retained on the Register as classed.			
Committee's Minute <u>16 January 1877</u>		M. Stewart R. N. R. Surveyor to Lloyd's Register of S.S. Shipping The 15 th Decr 1876. Certificate (if required).	
Character assigned <u>#A1</u>			

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____	Port of _____	Classed _____	
The present Condition of the			
Decks _____	Treenails _____	Windlass and Capstan _____	
Waterways _____	Breasthooks and Stemson _____	Pumps _____	
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____	
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____	
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____	
Plank sheers _____	Keelsons _____	Anchors, No. of _____	
Sheerstrakes _____	Clamps and Shelves _____	Cables _____	
Topsides _____	Ceiling _____	Hawsers and Warps _____	
Wales _____	Rudder _____	Standing and Running Rigging _____	
Plank (Bottom) and Counter _____	Copper _____ When put on _____		
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways _____	
Committee's Minute _____	18		
Character assigned _____			

