

ANNUAL SURVEYS.

No. in Reg. Book. **48** No. **25350** Survey held at **Liverpool** Date, first Survey **Nov 30** Last Survey **Dec 6** 18**76**
 on the **Iron Bk "Aberlady"** Master **J. Nichol**
 Tonnage **735** Built at **Dumbarton** When built **1875 - 9 mo**
 By whom built **Stenhouse** Owners **J. & J. Boyd**
 Port belonging to **Glasgow** Destined Voyage **Melbourne**
 If Surveyed Afloat or in Dry Dock **Afloat and in Canning dry dock**

Last Survey, No. **15342** Port of **Iron** Classed **100 A**
 Present Condition of the
 Decks **Good** **Transoms** **Rivets** **Good**
 Waterways **"** Breasthooks and Stemson **"**
 Comings **"** Transoms, ~~Pointers~~, and Crutches **"**
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
 Lower Deck Beams & Fastenings **"** ~~Ditto~~ ditto at other places **Not seen**
 Planksheers **"** Keelsons **Good**
 Sheerstrakes **"** Clamps and Shelves **"**
 Topsides **"** Ceiling **"**
 Wales **"** Rudder **"**
~~Plates~~ (Bottom) and Counter **"** Copper or Y.M. **Cen** When put on **75**
 Caulking of Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **"** Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Windlass and Capstan** **Good & efficient**
Pumps **"**
Boats **"**
Masts, Yards, &c. **"**
 Condition, how ascertained **Seen from deck**
Sails **Good**
Anchors, No. of **"**
Cables **and**
Hawsers and Warps **"**
Standing and Running Rigging **efficient**

The bottom scraped and painted. Is now in good condition and in my opinion eligible to remain as Classed.

Committee's Minute **Liverpool Jan^{ry} 19th 1877**

Character assigned **100 A**

M. L. W.

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** **18**

No. **1** Survey held at **Liverpool** Date, first Survey **Aug 5** Last Survey **Aug 13** 18**77**
 on the **Iron S "Dera"** Master **Chelley**
 Tonnage **761** Built at **Liverpool** When built **1873 - 5 mo**
 By whom built **Boyd** Owners **J. B. Walmsley**
 Port belonging to **Liverpool** Destined Voyage **America**
 If Surveyed Afloat or in Dry Dock **Afloat and in Canning dry dock**

Last Survey, No. **15772** Port of **Iron** Classed **100 A**
 Present Condition of the
 Decks **Good** **Transoms** **Rivets** **Good**
 Waterways **"** Breasthooks and Stemson **"**
 Comings **"** Transoms, ~~Pointers~~, and Crutches **"**
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
 Lower Deck Beams & Fastenings **"** ~~Ditto~~ ditto at other places **Not seen**
 Planksheers **"** Keelsons **Good**
 Sheerstrakes **"** Clamps and Shelves **"**
 Topsides **"** Ceiling **"**
 Wales **"** Rudder **"**
~~Plates~~ (Bottom) and Counter **"** Copper or Y.M. **Cen** When put on **73**
 Caulking of Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **"** Coal Bunkers, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Windlass and Capstan** **Good & efficient**
Pumps **"**
Boats **"**
Masts, Yards, &c. **"**
 Condition, how ascertained **Seen from deck**
Sails **Good**
Anchors, No. of **"**
Cables **and**
Hawsers and Warps **"**
Standing and Running Rigging **efficient**

The bottom scraped and painted. Is now in good condition and in my opinion eligible to remain as Classed.

Committee's Minute **Liverpool Jan^{ry} 19th 1877**

Character assigned **100 A**

M. L. W.

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** **18**

"Aberlady"

"Deva"

25360



© 2019

Lloyd's Register
Foundation