

ANNUAL SURVEYS.

25.905

No. 13965 Survey held at London Date, first Survey Recd 26.1.77 Last Survey Jan 20th 1877
 the BK Braganza Master _____
 Tonnage 601 Built at Glasgow When built 1875 1M
 By whom built uncan Owners A Rae
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

| Last Survey, No. <u>13965</u> Port of <u>Iron</u> | | Years assigned. | Character in Register Book. |
|---|---|---------------------|--|
| Condition of the | | Classed <u>100A</u> | <u>275</u> |
| Days | <u>good</u> Treenails Rivets <u>good</u> | | |
| | Breasthooks and Stenson <u>good</u> | | |
| | Transoms, Pointers, and Crutches <u>good</u> | | |
| Beams & Fastenings | Timbers of the Frame at the Openings <u>good</u> | | Windlass and Capstan |
| Trusses & Fastenings | Ditto ditto at other places <u>good</u> | | Pumps |
| | Keelsons <u>good</u> | | Boats |
| | Clamps and Shelves <u>good</u> | | Masts, Yards, &c. <u>good &</u> |
| | Ceiling <u>good</u> | | Condition, how ascertained <u>sufficient</u> |
| | Rudder <u>Bushed</u> <u>good</u> | | Sails <u>where</u> |
| | Copper or Y.M. Painted When put on <u>new</u> | | Anchors, No. of <u>3 Bar & 2 Pad</u> <u>they</u> |
| Bottom) and Counter | Caulking of Bottom, Deck, & Waterways <u>good</u> | | Cables <u>could</u> |
| Engine Room Skylights | Coal Bunker, Openings, Lids, &c. <u>good</u> | | Hawsers and Warps <u>be seen</u> |
| General Observations, Opinion as to Class, &c. | Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches <u>good</u> | | Standing and Running Rigging |

She is now in an efficient state of repair & entitled to remain as classed

Senhouse Martindale

Committee's Minute 2nd February 1877

Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18__

No. 15631 Survey held at London Date, first Survey _____ Last Survey Jan 12th 1877
 on the BK Primera Master W Sherwen
 Tonnage 597 Built at Glasgow When built 1875 1M
 By whom built Stephen Owners W Sherwen
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

| Last Survey, No. <u>15631</u> Port of <u>Iron</u> | | Years assigned. | Character in Register Book. |
|---|---|---------------------|--|
| Present Condition of the | | Classed <u>100A</u> | <u>1275</u> |
| Decks | <u>good</u> Treenails Rivets <u>good</u> | | |
| Waterways | Breasthooks and Stenson <u>good</u> | | |
| Openings | Transoms, Pointers, and Crutches <u>good</u> | | |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the Openings <u>good</u> | | Windlass and Capstan |
| Lower Deck Beams & Fastenings | Ditto ditto at other places <u>good</u> | | Pumps |
| Planksheers | Keelsons <u>good</u> | | Boats |
| Sheerstrakes | Clamps and Shelves <u>good</u> | | Masts, Yards, &c. <u>good &</u> |
| Oppsides | Ceiling <u>good</u> | | Condition, how ascertained <u>sufficient</u> |
| Yales | Rudder <u>good</u> | | Sails <u>where</u> |
| Plank (Bottom) and Counter | Copper or Y.M. Painted When put on <u>new</u> | | Anchors, No. of <u>3 Bar & 2 Pad</u> <u>they</u> |
| Engine Room Skylights | Caulking of Bottom, Deck, & Waterways <u>good</u> | | Cables <u>could</u> |
| General Observations, Opinion as to Class, &c. | Coal Bunkers, Openings, Lids, &c. <u>good</u> | | Hawsers and Warps <u>be seen</u> |
| | Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches <u>good</u> | | Standing and Running Rigging |

She is now in an efficient state of repair & entitled to remain as classed

Senhouse Martindale

Committee's Minute 2nd February 1877

Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18__

IRON470-0011

