

ANNUAL SURVEYS.

35.906

Recd 30.1.77

17669

No. 1598 Survey held at London Date, first Survey 1st January Last Survey 2nd January 1877
 in Book. on the "Loyle" Master Godhunter
 Tonnage 1598 Built at Sunderland When built 1874 - 9th mo
 By whom built Oswald Owners J. Fourse
 Port belonging to London Destined Voyage —
 If Surveyed Afloat or in Dry Dock Dry dock - Deptford Green

Last Survey, No. 15922 Port of Iron

Classed

Years assigned.

Character in Register Book.

100 A.1.
2.76

Present Condition of the

Good
 Waterways "
 Masts "
 Upper Deck Beams & Fastenings "
 Lower Deck Beams & Fastenings "
 Planksheers "
 Sheerstrakes "
 Topsides "
 Masts "
 Plating (Bottom) and Counter "

Treenails Rivets, where seen good
 Breasthooks and Stemson "
 Transoms, Pointers, and Crutches "
 Timbers of the Frame at the Openings "
 Ditto ditto at other places "
 Keelsons "
 Clamps and Shelves "
 Ceiling "
 Rudder "
 Copper or V.M. Paint When put on now
 Caulking of —
 Bottom, Deck, & Waterways good

Windlass and Capstan good
 Pumps "
 Boats 7 1/2 "
 Masts, Yards, &c. "
 Condition, how ascertained from the deck
 Sails good
 Anchors, No. of 3 B. 1 S. 2 K
 Cables good
 Hawseers and Warps "
 Standing and Running Rigging "

Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers " Cargo and Main Hatchways good Hatches "

General Observations, Opinion as to Class, &c. Surveyed with a portion of the outward cargo on board. Ship put into dry dock, bottom scraped and painted, and the rudder enlarged. She appeared to be in good condition and fit in my opinion to remain as classed. Fig: —

Committee's Minute 2nd February 1877

Character assigned 100 A.1 TRB

J. W. Scullard
 100 A.1.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

IRON 70-0036