

# ANNUAL SURVEYS.

35.906

Recd 23.1.77

No. in Reg. Book. on the **No.** 360 Survey held at **London** Date, first Survey **13/1/77** Last Survey **15 January 1877**  
**S.S. "Leio"** Master **Leahorne**  
 Tonnage **929** Built at **Lestri** When built **1874 - 3 mo**  
 By whom built **F. Oderso** Owners **St. Nav: Co. Nord.**  
 Port belonging to **London** Destined Voyage **—**  
 If Surveyed Afloat or in Dry Dock **Millwall dock dry dock**

Last Survey, No. **16683** Port of **Lion** Classed **100 A. 1.7.76**  
 Present Condition of the Decks **good**  
 Waterways **good**  
 Comings **good**  
 Upper Deck Beams & Fastenings **good**  
 Lower Deck Beams & Fastenings **good**  
 Planksheers **good**  
 Sheerstrakes **good**  
 Topsides **good**  
 Wales **good**  
 Plating (Bottom) and Counter **good**  
 Engine Room Skylights **good** Coal Bunker, Openings, Lids, &c. **good** Scuppers **good** Cargo and Main Hatchways **good** Hatches **good**  
 General Observations, Opinion as to Class, &c. **Bottom scraped and painted, Rudder hushed. Two additional iron pillars fitted under winch. Vessel is in good condition and fit to remain as classed.**

Committee's Minute **2<sup>nd</sup> February 1877** Character assigned **100 A.**  
 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) **TRW** Paid **18**

No. in Reg. Book. on the **No.** 517 Survey held at **London** Date, first Survey **13/1/77** Last Survey **15 January 1877**  
**S.S. "Tunis"** Master **Snch**  
 Tonnage **887** Built at **Newcastle** When built **1873 - 1 mo**  
 By whom built **Mitchell** Owners **Nelson, Bowker & Co**  
 Port belonging to **London** Destined Voyage **—**  
 If Surveyed Afloat or in Dry Dock **Deptford Green**

Last Survey, No. **16459** Port of **Lion** Classed **90 A. 1.4.76**  
 Present Condition of the Decks **good**  
 Waterways **good**  
 Comings **good**  
 Upper Deck Beams & Fastenings **good**  
 Lower Deck Beams & Fastenings **good**  
 Planksheers **good**  
 Sheerstrakes **good**  
 Topsides **good**  
 Wales **good**  
 Plating (Bottom) and Counter **good**  
 Engine Room Skylights **good** Coal Bunkers, Openings, Lids, &c. **good** Scuppers **good** Cargo and Main Hatchways **good** Hatches **good**  
 General Observations, Opinion as to Class, &c. **A few rivets renewed in rudder - Bottom scraped and painted. She now appears in good condition and fit to remain as classed.**

Committee's Minute **2<sup>nd</sup> February 1877** Character assigned **90 A.**  
 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) **TRW** Paid **18**