

ANNUAL SURVEYS.

35,950

No. in Reg. Book. **675** No. **1231** Survey held at **London** Date, first Survey **22nd Jan'y** Last Survey **28th Jan'y** 1877
 on the Ship **Sir Henry Lawrence** Master **Roberts**
 Tonnage **1221** Built at **Liverpool** When built **1865-4 mo**
 By whom built **Lloyd** Owners **J. Jardine**
 Port belonging to **Liverpool** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Pontoons Victoria Dock.**

Last Survey, No. **12636** Port of **Iron** Classed **S.S. Liv No 2-74.** Years assigned. **4-74.** Character in Register Book. **A.1.**
 Present Condition of the
 Decks **Good** Treeneails **Rivets** **Good**
 Waterways **—** Breasthooks and Stems **—**
 Comings **—** Transoms, Pointers, and Crutches **—**
 Upper Deck Beams & Fastenings **—** Timbers of the Frame at the Openings **—**
 Lower Deck Beams & Fastenings **—** Ditto ditto at other places **—**
 Planksheers **—** Keelsons **—**
 Sheerstrakes **—** Clamps and Shelves **—**
 Topsides **—** Ceiling **—**
 Wals **—** Rudder **—**
 Plate (Bottom) and Counter **—** Copper or Y.M. **Cent** When put on **1865**
 Caulking of Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **—** Coal Bunker, Openings, Lids, &c. **—** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Bottom and Keel sighted, coated with Paint and Tallow and the topsides with Paint.**

This Vessel is now in good and efficient condition and eligible to remain as Classed.

Committee's Minute **20th February 1877** Character assigned **A.1.** Surveyor to Lloyd's Register of British and Foreign Shipping. **Thos Wm Blasell.** Certificate (if required) **—** Paid **18**

No. in Reg. Book. **176** No. **1146** Survey held at **London** Date, first Survey **3rd Feby** Last Survey **3rd Feby** 1877
 on the Ship **"The Bruce"** Master **J. Southcott.**
 Tonnage **1200** Built at **Glasgow** When built **1866-10 mo**
 By whom built **Aitken** Owners **Brit. Sh. Own. Co. Lim.**
 Port belonging to **Liverpool** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Blackwall Point by dock.**

Last Survey, No. **15674** Port of **Iron** Classed **S.S. Lon No 2-74** Years assigned. **1-76.** Character in Register Book. **A.1.**
 Present Condition of the
 Decks **Rivets** Treeneails **Rivets** **Good**
 Waterways **—** Breasthooks and Stems **—**
 Comings **—** Transoms, Pointers, and Crutches **—**
 Upper Deck Beams & Fastenings **—** Timbers of the Frame at the Openings **—**
 Lower Deck Beams & Fastenings **—** Ditto ditto at other places **—**
 Planksheers **—** Keelsons **—**
 Sheerstrakes **—** Clamps and Shelves **—**
 Topsides **—** Ceiling **—**
 Wals **—** Rudder **—**
 Plate (Bottom) and Counter **—** Copper or Y.M. **Cent** When put on **1866**
 Caulking of Bottom, Deck, & Waterways **Good**
 Engine Room Skylights **—** Coal Bunkers, Openings, Lids, &c. **—** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Bottom and Keel sighted cleaned and coated with Patent Composition, and the topsides with Paint.**

This Vessel is now in good and efficient condition, and eligible to remain as Classed.

Committee's Minute **20th February 1877** Character assigned **A.1.** Surveyor to Lloyd's Register of British and Foreign Shipping. **Thos Wm Blasell.** Certificate (if required) **—** Paid **18**