

ANNUAL SURVEYS.

17838

Rec 27/2/19

No. 73 Survey held at Calcutta Date 19th January 1877
 on the S.S. Africa Master Patterson
 Tonnage 2032 Built at Dumbarton When built 1874-4 mo
 By whom built Denney Owners B. J. S. Navigation Coy
 Port belonging to Glasgow Destined Voyage Coast
 If Surveyed Afloat or in Dry Dock in dry Dock and Afloat

Last Survey, No. 5th March 74 Port of Dumbarton Iron Classed 100 A1

The present Condition of the

Decks good when seen	Treenails Revetting good when seen	Windlass and Capstan good, Patent
Waterways "	Breasthooks and Stemson "	Pumps in good order
Comings "	Transoms, Pointers, and Crutches "	Boats 6, all sound
Upper Deck Beams & Fastenings "	Timbers of the Frame at the Openings "	Masts, Yards, &c. all good
Lower Deck Beams & Fastenings "	Ditto ditto at other places "	Sails 2 Suit
Planksheers Slating "	Keelsons "	Anchors, No. of 3 Bower, 1 Stream 2 Kedges
Sheerstrakes "	Clamps and Shelves "	Cables 270 Bower 90 fathoms Stream
Topsides "	Ceiling "	Hawsers and Warps 6 assorted
Wales "	Rudder good & well hung	Standing and Running Rigging all good
Plank (Bottom) and Counter "	Copper Paint When put on Jan 77	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

A strong well built Iron Steamer (has been recommended to scale and paint inside) and is in my opinion fit to be retained on the Register as Classed.

Committee's Minute 2nd March 18 77

Character assigned 100 A1 J.B.W.

6248- MZ

M Stewart R.N.R.
 Surveyor to Lloyd's Register of B. & F. Shipping.
 Port of Calcutta
 Dec 26 January 1877.
 Certificate (if required).

No. Survey held at Date 18
 on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute 18

Character assigned

