

ANNUAL SURVEYS.

No. 75 Survey held at Glasgow Date 14th February 1877
 on the B^e Henry Dempie Master Ballmann
 Tonnage 175/197 Built at Glasgow When built 1869 7 mo.
 By whom built Stephens Owners H. Foerster
 Port belonging to Bordeaux Destined Voyage —
 If Surveyed ~~Afloat~~ in Dry Dock Citrouille's No. 2

Rec 20/2/77

Last Survey, No. 11538 Port of Leon Classed * A 1
 S.S. No. 33 6.33

The present Condition of the

Decks	<u>Keels</u>	Windlass and Capstan
Waterways	<u>Treenails</u>	Pumps
Comings	Breasthooks and Stemson	Boats
Upper Deck Beams & Fastenings	Transoms, Pointers, and Crutches	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Timbers of the Frame at the Openings	Sails
Planksheers	Ditto ditto at other places	Anchors, No. of
Sheerstrakes	Keelsons	Cables
Topsides	Clamps and Shelves	Hawsers and Warps
Wales	Ceiling	Standing and Running Rigging
Plank (Bottom) and Counter	Rudder	
	Copper	
	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Satisfactorily

*Bottom scraped and coated with composition, is now in an efficient condition and in my opinion eligible to remain as classed * A 1.*

Committee's Minute 23rd February 1877

Character assigned * A 1

E. Capelle
Surveyor to Lloyd's Register of Shipping.
 Certificate (if required).

TRW

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper	
	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18

Character assigned _____



© 2019

Lloyd's Register
 Foundation
 Certificate (if required).