

No. Survey held at London Date, first Survey 23 Feb 17 Last Survey 26 Feb 18 1877
No. in Reg. Book. on the S. Loch Kilmachar 1798 Master F. Wagstaff
591 Tonnage 1485 Built at Glasgow When built 1845. 8 mo
By whom built Thompson Owners Glasgow Shipping Co.
Port belonging to Glasgow Destined Voyage
If Surveyed Afloat or in Dry Dock Deptford Green Dry Dock

Last Survey, No. 13-045 Port of Iron Classified Years assigned. Character in Register Book. 100 A 1
9. 75

Present Condition of the	Decks	Treenails	Rivets	Good where seen
Waterways	<u>Go</u>	Breasthooks and Stemson	<u>Go</u>	
Comings	<u>Go</u>	Transoms, Pointers, and Crutches	<u>Go</u>	
Upper Deck Beams & Fastenings	<u>Go</u>	Timbers of the Frame at the Openings	<u>Go</u>	
Lower Deck Beams & Fastenings	<u>Go</u>	Ditto ditto at other places	<u>Go</u>	
Planksheers	<u>Go</u>	Keelsons	<u>Go</u>	
Sheerstrakes	<u>Go</u>	Clamps and Shelves	<u>Go</u>	
Topsides	<u>Go</u>	Ceiling	<u>Go</u>	
Wales	<u>Go</u>	Rudder	<u>Go</u>	
Plating (Bottom) and Counter	<u>Go</u>	Coating Copper or V.M.	<u>Good</u>	When put on <u>how</u>
		Caulking of Bottom, Deck, & Waterways	<u>Good</u>	
Engine Room Skylights	<u> </u>	Coal Bunkers, Openings, Lids, &c.	<u> </u>	Scuppers <u>Go</u> Cargo and Main Hatchways <u>Go</u> Hatches <u>Go</u>

General Observations, Opinion as to Class, &c. She has now been put into dry dock and her bottom scraped and properly coated.
She is now in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 9th March 1877
Character assigned 100 A 1
Surveyor to Lloyd's Register of British and Foreign Shipping. J. H. H. H.
Certificate (if required) Paid 1877

IRON 470-0456