

ANNUAL SURVEYS.

Rec 2/4/77

No. in Reg. Book. **334** No. **4531** Survey held at **Hull** Date, first Survey **7th March** Last Survey **17th March** 18**77**
 on the **Iron Steamer Don Antonio** Master **Perscheirs**
 Tonnage **1109** Built at **Glasgow** When built **1860**
 By whom built **Hill** Owners **Bailey & Leethams**
 Port belonging to **Lisbon** Destined Voyage **Lisbon**
 If Surveyed Afloat or in Dry Dock **On H. J. Norris slipway & afloat in Albert Dock**

Last Survey, No. **16736** Port of **Liverpool** Classified **S.S. Hul 11-2-75** Years assigned **5-76** Character in Register Book **100 A 1**
 Present Condition of the Decks **Good**
 Waterways **Good**
 Comings **Good**
 Upper Deck Beams & Fastenings **Good**
 Lower Deck Beams & Fastenings **Good**
 Planksheers **Good**
 Sheerstrakes **Good**
 Topsides **Good**
 Wales **Good**
 Plank (Bottom) and Counter **Good**
 Breasthooks and Stemson **Good**
 Transoms, Pointers, and Crutches **Good**
 Timbers of the Frame at the Openings **Good**
 Ditto ditto at other places **Good**
 Keelsons **Good**
 Clamps and Shelves **Good**
 Ceiling **Good**
 Rudder **Good**
 Copper or V.M. **Good**
 Caulking of Bottom, Deck, & Waterways **Good**
 Windlass and Capstan **Good**
 Pumps **Good**
 Boats **Good**
 Masts, Yards, &c. **Good**
 Condition, how ascertained **by Sounding**
 Sails **Complete Sails & Tacks**
 Anchors, No. of **3 B 18 & 2 K 12**
 Cables **300 fms**
 Hawser and Warps **Good**
 Standing and Running Rigging **Good**
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Bottom cleaned and painted**

Is eligible in my opinion to remain as classed 100 A 1

Committee's Minute **3 April** 18**77**
 Character assigned **100 A 1**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18**77**

No. in Reg. Book. **20** No. **14650** Survey held at **Hull** Date, first Survey **5th March** Last Survey **18th March** 18**77**
 on the **Iron Steamer Abbey Cowper** Master **Hay**
 Tonnage **726** Built at **Sunderland** When built **1875**
 By whom built **689** **Datford** Owners **Hay & Co**
 Port belonging to **Liverpool** Destined Voyage **London**
 If Surveyed Afloat or in Dry Dock **Corporation Graving Dock**

Last Survey, No. **14650** Port of **Liverpool** Classified **S.S. Hul 11-2-75** Years assigned **6-75** Character in Register Book **100 A 1**
 Present Condition of the Decks **Good**
 Waterways **Good**
 Comings **Good**
 Upper Deck Beams & Fastenings **Good**
 Lower Deck Beams & Fastenings **Good**
 Planksheers **Good**
 Sheerstrakes **Good**
 Topsides **Good**
 Wales **Good**
 Plank (Bottom) and Counter **Good**
 Breasthooks and Stemson **Good**
 Transoms, Pointers, and Crutches **Good**
 Timbers of the Frame at the Openings **Good**
 Ditto ditto at other places **Good**
 Keelsons **Good**
 Clamps and Shelves **Good**
 Ceiling **Good**
 Rudder **Good**
 Copper or V.M. **Good**
 Caulking of Bottom, Deck, & Waterways **Good**
 Windlass and Capstan **Good**
 Pumps **Good**
 Boats **Good**
 Masts, Yards, &c. **Good**
 Condition, how ascertained **by Sounding**
 Sails **Good**
 Anchors, No. of **3 B 18 & 2 K 12**
 Cables **300 fms**
 Hawser and Warps **Good**
 Standing and Running Rigging **Good**
 Engine Room Skylights **Good** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Bottom cleaned and painted**

Is eligible in my opinion to remain as classed 100 A 1

Committee's Minute **3 April** 18**77**
 Character assigned **100 A 1**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18**77**

IRON 470-0530