

# ANNUAL SURVEYS.

18069

Recd 14/1/77

No. in Reg. Book. **No. 3796** Survey held at Whitby Date, first Survey \_\_\_\_\_ Last Survey 31<sup>st</sup> March 1877  
 on the Sea St. "Lady Hilary" Master W. Nicholson  
 Tonnage 269 Built at Whitby When built 1846  
 By whom built Turnbull Owners Whitby Steam Ship Co.  
 Port belonging to Whitby Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock In the Harbour

Last Survey, No. 15949 Port of Leam Years assigned. 90 A1 Character in Register Book  
 Present Condition of the Decks Good 3/46  
 Waterways "  
 Comings "  
 Upper Deck Beams & Fastenings Good  
 Lower Deck Beams & Fastenings "  
 Planksheers \_\_\_\_\_  
 Sheerstrakes Good  
 Topsides "  
 Wales "  
 Plank (Bottom) and Counter Good where seen  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom cleaned down & coated with paint & black varnish inside with paint. Stern bush repaired Propeller new.  
Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion remain as now classed 90 A1.

Committee's Minute 10<sup>th</sup> April 1877 S. P. Gladstone  
 Character assigned 90 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book  
 Present Condition of the Decks \_\_\_\_\_  
 Waterways \_\_\_\_\_  
 Comings \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_  
 Planksheers \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_  
 Topsides \_\_\_\_\_  
 Wales \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18

