

# ANNUAL SURVEYS.

No. in Reg. Book. **453** No. **1041** Survey held at **London** Date, first Survey **20/3/77** Last Survey **22 March** 1877  
 on the **S. Duchess of Edinburgh** Master **Peter**  
 Tonnage **1693** Built at **Sunderland** When built **1874** 7 mo.  
 By whom built **Mounsey** Owners **T. S. Watson**  
 Port belonging to **London** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Green's Upper Dry Dock**

Last Survey, No. **14041** Port of **Iron** Classed **100A1** Years assigned **3.75** Character in Register Book.  
 Present Condition of the Decks **Good** Rivets **Good where seen**  
 Waterways **do** Breasthooks and Stemson **do**  
 Comings **do** Transoms, Pointers, and Crutches **do**  
 Upper Deck Beams & Fastenings **do** Timbers of the Frame at the Openings **do**  
 Lower Deck Beams & Fastenings **do** Ditto ditto at other places **do**  
 Planksheers **do** Keelsons **do**  
 Sheerstrakes **do** Clamps and Shelves **do**  
 Topsides **do** Ceiling **do**  
 Wales **do** Rudder **Good**  
 Plating (Bottom) and Counter **do** Copper on **Bottom** When put on **Now**  
 Caulking of Bottom, Deck, & Waterways **Good**  
 Engine Room Skylights **do** Coal Bunker, Openings, Lids, &c. **do** Scuppers **do** Cargo and Main Hatchways **Good** Hatches **do**  
 General Observations, Opinion as to Class, &c.

This ship is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute **6th April** 1877 Character assigned **100A1** Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) **TRW** Paid **18**

No. in Reg. Book. **962** No. **14047** Survey held at **London** Date, first Survey **22/3/77** Last Survey **23 March** 1877  
 on the **S. Star of Greece** Master **Shaw**  
 Tonnage **1227** Built at **Belfast** When built **1868** 9 mo.  
 By whom built **Harland** Owners **J. Corry & Co**  
 Port belonging to **Belfast** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Green's Upper Dry Dock**

Last Survey, No. **14047** Port of **Iron** Classed **\*A1** Years assigned **8.76** Character in Register Book.  
 Present Condition of the Decks **Good** Rivets **Good where seen**  
 Waterways **do** Breasthooks and Stemson **do**  
 Comings **do** Transoms, Pointers, and Crutches **do**  
 Upper Deck Beams & Fastenings **do** Timbers of the Frame at the Openings **Good**  
 Lower Deck Beams & Fastenings **do** Ditto ditto at other places **where seen**  
 Planksheers **do** Keelsons **do**  
 Sheerstrakes **do** Clamps and Shelves **do**  
 Topsides **do** Ceiling **do**  
 Rudder **Good**  
 Coated Copper on **F.M.** When put on **Now**  
 Caulking of Bottom, Deck, & Waterways **Good**  
 Engine Room Skylights **do** Coal Bunkers, Openings, Lids, &c. **do** Scuppers **do** Cargo and Main Hatchways **Good** Hatches **do**  
 General Observations, Opinion as to Class, &c.

This vessel is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute **6th April** 1877 Character assigned **100A1** Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) **TRW** Paid **18**