

ANNUAL SURVEYS.

No. in Reg. Book. on the **No. 3797** Survey held at **West Hartlepool** Date, first Survey **20th March** Last Survey **20th March** 18**77**
107 Tonnage **1611** Built at **West Hartlepool** Master **J. Besley**
 By whom built **J. Irvine** Owners **R. Irvine & Co.**
 Port belonging to **West Hartlepool** Destined Voyage
 If Surveyed Afloat or in Dry Dock **In Dry Dock**

Last Survey, No. **17110** Port of **Iron** Classed **90 A1**
 Present Condition of the Decks **Good** S.S. Hpl. No. **1-75** 9/76
 Waterways **Good**
 Comings **Good**
 Upper Deck Beams & Fastenings **Good**
 Lower Deck Beams & Fastenings **Good**
 Plank (Bottom) and Counter **Good**
 Sheerstrakes **Good**
 Topsides **Good**
 Wales **Good**
 Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Now done bottom cleaned down & coated with paint & black varnish**
Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion remain as now
Classed 90 A1
S.S. Hpl. No 1-75

Committee's Minute **10th April** 18**77** **S. R. Gladstone**
 Character assigned **90 A1** **DRW** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18

No. in Reg. Book. on the **No. 366** Survey held at **West Hartlepool** Date, first Survey **24 March** Last Survey **24 March** 18**77**
366 Tonnage **1520** Built at **Hartlepool** Master **Snowden**
 By whom built **W. H. H. & Co.** Owners **West Hartlepool Steam Nav. Co.**
 Port belonging to **West Hartlepool** Destined Voyage **Fibralta**
 If Surveyed Afloat or in Dry Dock **In Dry Dock**

Last Survey, No. **16667** Port of **Iron** Classed **90 A1**
 Present Condition of the Decks **Good** S.S. Hpl. No. **1-74** 6.76
 Waterways **"**
 Comings **"**
 Upper Deck Beams & Fastenings **Good**
 Lower Deck Beams & Fastenings **"**
 Plank (Bottom) and Counter **Good**
 Sheerstrakes **Good**
 Topsides **"**
 Wales **"**
 Engine Room Skylights **Good** Coal Bunkers, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Now done bottom cleaned down & coated with paint & varnish**
Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion remain as now
Classed 90 A1
S.S. Hpl. No 1-74

Committee's Minute **10th April** 18**77** **S. R. Gladstone**
 Character assigned **90 A1** **DRW** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18