

ANNUAL SURVEYS.

Recd: 4 April 1877
26.08.21

1875

No. in Reg. Book. **No.** 476 on the *S.S. "Freja"* Survey held at *London* Date, first Survey *22 March* Last Survey *22 March* 18 *77*
 Tonnage *872* Built at *Glasgow* When built *1875* 5 mo.
 By whom built *Aitken* Owners *Campskibe & Co.*
 Port belonging to *Copenhagen* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *Fletcher's dry dock*

Last Survey, No. *15439* Port of *London Iron* Classed *95-A*
 Years assigned. *176* Character in Register Book.

Present Condition of the Decks _____ Waterways _____ Comings _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Planksheers _____ Sheerstrakes _____ Topsides _____ Wales _____ Plank (Bottom) and Counter _____ Engine Room Skylights _____ General Observations, Opinion as to Class, &c. _____	<i>Keels</i> <i>Keels</i> Breasthooks and Stemson _____ Transoms, Pointers, and Crutches _____ Timbers of the Frame at the Openings _____ Ditto ditto at other places _____ Keelsons _____ Clamps and Shelves _____ Ceiling _____ Rudder _____ Copper or Y.M. _____ When put on _____ Caulking of Bottom, Deck, & Waterways _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____	Windlass and Capstan _____ Pumps _____ Boats _____ Masts, Yards, &c. _____ Condition, how ascertained _____ Sails _____ Anchors, No. of _____ Cables _____ Hawsers and Warps _____ Standing and Running Rigging _____ Cargo and Main Hatchways _____ Hatches _____
---	--	--

Bottom cleaned and recoated.
 This vessel appears in good condition and eligible to remain as classed

Committee's Minute *6th April* 18 *77* *J. P. Cougdon*
 Character assigned *95A*
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. **No.** *218* on the *S.S. "Despatch"* Survey held at *London* Date, first Survey *26th Mar* Last Survey *26th March* 18 *77*
 Tonnage *495* Built at *Newcastle* When built *1863* 12 mo.
 By whom built *78* *Smith* Owners *Fenwick & Son*
 Port belonging to *London* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *Smith's dock*

Last Survey, No. *14984* Port of *Iron* Classed _____
 Years assigned. _____ Character in Register Book. *95-A*

Present Condition of the Decks _____ Waterways _____ Comings _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Planksheers _____ Sheerstrakes _____ Topsides _____ Wales _____ Plank (Bottom) and Counter _____ Engine Room Skylights _____ General Observations, Opinion as to Class, &c. _____	<i>Keels</i> <i>Keels</i> Breasthooks and Stemson _____ Transoms, Pointers, and Crutches _____ Timbers of the Frame at the Openings _____ Ditto ditto at other places _____ Keelsons _____ Clamps and Shelves _____ Ceiling _____ Rudder _____ Copper or Y.M. _____ When put on _____ Caulking of Bottom, Deck, & Waterways _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____	Windlass and Capstan _____ Pumps _____ Boats _____ Masts, Yards, &c. _____ Condition, how ascertained _____ Sails _____ Anchors, No. of _____ Cables _____ Hawsers and Warps _____ Standing and Running Rigging _____ Cargo and Main Hatchways _____ Hatches _____
---	--	--

Bottom cleaned and recoated.
 This vessel appears in good condition and eligible to remain as classed

Committee's Minute *6th April* 18 *77* *J. P. Cougdon*
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

H60-111014

Frya
D
Despatch



© 2019

Lloyd's Register
Foundation