

1864
ANNUAL SURVEYS.

No. 22

Survey held at

Port Adelaide

Date

7th Feb

1864

On the *Berque Queen of the South*

Master

Miles

Tonnage *376*

Built at

Scanderland

When built

11^{mo} 1864

By whom built

Pile

Owners

Buxton & Co

Port belonging to

Lyttelton N.Z.

Destined Voyage

Colonial

If Surveyed Afloat or in Dry Dock

Potent Ties

Last Survey, No. *1011*

Port of

Imm

Classed

** A.1*

The present Condition of the

Decks

Good

Treenails

"

Windlass and Capstan

Good

Waterways

"

Breasthooks and Stemson

Good

Pumps

"

Comings

"

Transoms, Pointers, and Crutches

"

Boats

"

Upper Deck Beams & Fastenings

"

Timbers of the Frame at the Openings

Masts, Yards, &c.

"

Lower Deck Beams & Fastenings

"

Ditto ditto at other places

Sails

Well found

Planksheers

"

Keelsons

"

Anchors, No. of *3 Bowers 1 Stream 1 Head*

Sheerstrakes

"

Clamps and Shelves

"

Cables

240 fms

Topsides

"

Ceiling

New

Hawsers and Warps *Sufficient*

Wales

"

Rudder

Good

Standing and Running Rigging *Good*

Plank (Bottom) and Counter

"

Copper

When put on

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

I have examined this vessel's bottom, which was good with the exception of one rotten board which has been renewed; I have had all the ceiling removed from her floor, all the cement examined and renewed where required; the mast has all been taken of the Bower and Head, and painted, new Ceiling, Windlass on hung, Chains changed, I would recommend L. J. P. M. to be put in sufficient time for S. T. N. 3

Committee's Minute

18

Character assigned

** A.1*

W. J. P. M.

Surveyor to Lloyd's Register Certificate (if required).

No. *4020*

Survey held at

Date

18

on the

Master

Tonnage

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

The present Condition of the

Decks

Treenails

Windlass and Capstan

Waterways

Breasthooks and Stemson

Pumps

Comings

Transoms, Pointers, and Crutches

Boats

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Masts, Yards, &c.

Lower Deck Beams & Fastenings

Ditto ditto at other places

Sails

Planksheers

Keelsons

Anchors, No. of

Sheerstrakes

Clamps and Shelves

Cables

Topsides

Ceiling

Hawsers and Warps

Wales

Rudder

Standing and Running Rigging

Plank (Bottom) and Counter

Copper

When put on

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute

18

Character assigned



© 2019

Lloyd's Register
Foundation
Certificate (if required).