

# ANNUAL SURVEYS.

1827

No. in Reg. Book. **323** No. **3010** Survey held at West Hartlepool Date, first Survey 21<sup>st</sup> April Last Survey 24<sup>th</sup> April 1877  
 on the Ship "Castle Holme" Master J. Williamson  
 Tonnage 998 Built at Sunderland When built 1875 - 9 mo  
 By whom built Barton Owners Hine Bros  
 Port belonging to Maryport Destined Voyage Singapore  
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 1535 Port of Iron Classed 100 A1  
 Present Condition of the Decks Good  
 Waterways Good  
 Comings Good  
 Upper Deck Beams & Fastenings Good  
 Lower Deck Beams & Fastenings Good  
 Plank sheers Good  
 Sheerstrakes Good  
 Topsides Good  
 Wales Good  
 Plank (Bottom) and Counter Good  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom cleaned down & coated with Paint & Palkow  
Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the world & may in my opinion remain as now classed 100 A1

Committee's Minute 8<sup>th</sup> May 1877  
 Character assigned 100 A1  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 1877

No. in Reg. Book. **48** No. **435** Survey held at West Hartlepool Date, first Survey 28 April Last Survey 28 April 1877  
 on the Ship "Palma" Master B. Murrell  
 Tonnage 1441 Built at Hartlepool When built 1874 - 11 mo  
 By whom built Withy Owners H. Herbrand  
 Port belonging to West Hartlepool Destined Voyage Singapore  
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 15835 Port of Iron Classed 90 A1  
 Present Condition of the Decks Good  
 Waterways "  
 Comings "  
 Upper Deck Beams & Fastenings Good  
 Lower Deck Beams & Fastenings "  
 Plank sheers Good  
 Sheerstrakes Good  
 Topsides "  
 Wales "  
 Plank (Bottom) and Counter Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom cleaned down & coated with Paint & Palkow  
Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the world & may in my opinion remain as now classed 90 A1

Committee's Minute 8<sup>th</sup> May 1877  
 Character assigned 90 A1  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 1877