

ANNUAL SURVEYS.

No. in Reg. Book. on the **No.** 757 Survey held at London Date, first Survey 19/4/77 Last Survey 23rd April 1877
 Ship "City of Corinth" Master Taylor
 Tonnage 229/1276/1190 Built at Glasgow When built 1870 - 2nd mo
 By whom built Barclay Owners Geo Smith & son
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Walker's dry dock

Read 25.4.77.

Last Survey, No. 15018 Port of Iron
 Present Condition of the Decks Good
 Waterways _____
 Comings _____
 Upper Deck Beams & Fastenings _____
 Lower Deck Beams & Fastenings _____
 Planksheers _____
 Sheerstrakes _____
 Topsides _____
 Wales _____
 Plank (Bottom) and Counter _____
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____
 General Observations, Opinion as to Class, &c. _____

Transoms Ruets where seen Good
 Breasthooks and Stemson _____
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame at the Openings _____
 Ditto ditto at other places _____
 Keelsons _____
 Clamps and Shelves _____
 Ceiling _____
 Rudder _____
 Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps _____
 Boats 4 No _____
 Masts, Yards, &c. _____
 Condition, how ascertained from the deck
 Sails Good
 Anchors, No. of 5 B - 1 S - 2 K
 Cables part seen Good
 Hawser and Warps _____
 Standing and Running Rigging _____
 Cargo and Main Hatchways Good Hatches _____

Surveyed with cargo in the lower hold.
 Vessel placed in dry dock, bottom cleaned and painted.
 Rudder brushed.
 This ship appears to be in good condition and fit in my opinion to remain as classed Fig. 1 - A.I.
 Committee's Minute 1st May 1877
 Character assigned A.I.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. on the **No.** 71 Survey held at London Date, first Survey 20/4/77 Last Survey 23rd April 1877
 Ship "Pannure" Master Downie
 Tonnage 505/181/1096 Built at Glasgow When built 1875 - 6 mo
 By whom built Stephen Owners David Bruce
 Port belonging to Dundee Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Millwall graving dock

Last Survey, No. 16309 Port of Iron
 Present Condition of the Decks Good
 Waterways _____
 Comings _____
 Upper Deck Beams & Fastenings _____
 Lower Deck Beams & Fastenings _____
 Planksheers _____
 Sheerstrakes _____
 Topsides _____
 Wales _____
 Plank (Bottom) and Counter _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____
 General Observations, Opinion as to Class, &c. _____

Transoms Ruets where seen Good
 Breasthooks and Stemson _____
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame at the Openings _____
 Ditto ditto at other places _____
 Keelsons _____
 Clamps and Shelves _____
 Ceiling _____
 Rudder _____
 Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps _____
 Boats 6 No _____
 Masts, Yards, &c. _____
 Condition, how ascertained from the deck
 Sails Good
 Anchors, No. of 3 B - 1 S - 2 K
 Cables part seen Good
 Hawser and Warps _____
 Standing and Running Rigging _____
 Cargo and Main Hatchways Good Hatches Good

Surveyed with ballast on board.
 Bottom cleaned and painted.
 Vessel appears to be in good condition and is eligible in my opinion to remain as classed Fig. 100 A.I.
 Committee's Minute 1st May 1877
 Character assigned 100 A.I.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____