

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 25535** Survey held at **Liverpool** Date, first Survey **12th April** Last Survey **19th April** 1877
193 on the **S.S. "Fire Queen"** Master **Burley**
 Tonnage under Tonnage Deck **697** Built at **Hartlepool** When built **1864** YEAR. MONTH. **10**
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage **1172** Owners **J. I. Harrison** Port belonging to **Liverpool**
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St^rmer, cut on Bm. **797** Residence **Liverpool**
 By whom built **Pile** Destined Voyage **Pemambuco**
 If Surveyed Afloat or in Dry Dock **Brunswick. G. St. and afloat.**

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. **1** Character in Register Book. **A 1**
 Last Survey, No. **24721** Port **Liverpool** Classed **SS Liverpool No 1-1870**

REPAIRS, OR EXAMINATION AS PER RULE **for S.S. No 3.**
The bottom ex^d found good. scraped, cleaned and painted.

The further requirements for S.S. No 3 were communicated to the Superintendent and by letter to the owner, but up to this time no further opportunity has been afforded us of completing the survey and the vessel has now proceeded to sea.
Please see owners letter of the 19th Feb 1877.

Letter of the 19th Feb^r 1877 received from owner, and copy advised to London in my letter of the 20/2/77. J.F.P.

Present Condition of the Decks	Freeboards Rivets	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Water	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper Cement When put on 1864	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations, Opinion as to Class, &c.
We are of opinion that the class of this vessel should be omitted from the Register and marked — in red.

The Amount of Entry Fee ... £ ... received by me, }
 Special ... £ ... 187
 Certificate (if required) ... £ ...
 (Travelling Expenses, if any, £ ...)
 Committee's Minute **Liverpool Apr^l 27-1877.**
 Character assigned **Expunge Character with Red**
20/2/77 to the Dept
Ryels
J. G. Wingham
 Surveyor to Lloyd's Register of British and Foreign Shipping.
Edw. Wheeler
 Lloyd's Register Foundation
 IRON 471-0343

REPORT OF SURVEY FOR ABSTRACTS, ETC.

"Fire Lubber" 255357



© 2019

Lloyd's Register
Foundation