

# ANNUAL SURVEYS.

No. in Reg. Book. 673 No. 14723 Survey held at London Date, first Survey 17/4/77 Last Survey 17/4/77 1877  
 on the S.S. London Master J. Harris  
 Tonnage 831 Built at Newcastle When built 1862 3 mo  
 By whom built Leslie Owners J. Hall Jr & Co  
 Port belonging to London Destined Voyage Cadiz  
 If Surveyed Afloat or in Dry Dock London Docks afloat

Last Survey, No. 14723 Port of Iron Classed S.S. Lon. No. 3. 73 100 A 1  
 Present Condition of the Decks Good Rivets Good Treenails Good  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers do Keelsons do  
 Sheerstrakes do Clamps and Shelves do  
 Topsides do Ceiling do  
 Wales do Rudder do  
 Plating (Bottom) and Counter do Copper or V.M. When put on  
 Caulking of Bottom, Deck, & Waterways do  
 Engine Room Skylights do Coal Bunker, Openings, Lids, &c. Good Scuppers do Cargo and Main Hatchways do Hatches do  
 General Observations, Opinion as to Class, &c.

*This vessel is now in a good and efficient condition and eligible in our opinion to remain as classed.*

Committee's Minute 8th May 18 77  
 Character assigned 100 A 1

J. Shearler  
S. Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18 77

No. in Reg. Book. 40 No. 14879 Survey held at London Date, first Survey 9/4/77 Last Survey 25/4/77 18 77  
 on the S.S. Galicia Master R. Valder  
 Tonnage 570 Built at Hartlepool When built 1866 4 mo  
 By whom built Richardson Owners J. Hall Jr & Co  
 Port belonging to London Destined Voyage Cadiz  
 If Surveyed Afloat or in Dry Dock London Docks - afloat

Last Survey, No. 14879 Port of Iron Classed S.S. Lon. No. 2. 74 100 A 1  
 Present Condition of the Decks Good Rivets Good Treenails Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " ~~Timbers of the~~ Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plating (Bottom) and Counter " Copper or V.M. When put on  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers do Cargo and Main Hatchways Good Hatches do  
 General Observations, Opinion as to Class, &c.

*This vessel is now in a good and efficient condition and eligible in our opinion to remain as classed.*

Committee's Minute 8th May 18 77  
 Character assigned A 1

J. Shearler  
S. Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18 77

180N471-0364