

ANNUAL SURVEYS.

No. in Reg. Book. **No.** *1013* Survey held at *London* Date, first Survey *6th April* Last Survey *6th April* 18 *77*
3 on the *S. "Oatlands"* Master *Lawrence*
 Tonnage *955* Built at *Dundee* When built *1846*
 By whom built *Gourley* Owners *Lawrence*
 Port belonging to *London* Destined Voyage
 If Surveyed Afloat or in Dry Dock *Carters dock*

Last Survey, No. *14538* Port of *Iron*

Classed *100 A1*
 Years assigned. *10.76*
 Character in Register Book.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treeails Quite new seen good
 Breasthooks and Stemson *de de*
 Transoms, Pointers, and Crutches *de de*
 Timbers of the Frame at the Openings *de de*
 Ditto ditto at other places *de de*
 Keelsons *de de*
 Clamps and Shelves *de de*
 Ceiling *de de*
 Rudder *de*
 Copper or Y.M. *—* When put on *—*
 Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

good

and

complete

Bottom cleaned and recoated.

This vessel appears in good condition and eligible to remain as classed.

Surveyed with port outward Cargo on board

Committee's Minute *8th May* 18 *77* *Thos. Congdon*

Character assigned *100 A1*

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. in Reg. Book. **No.** *701* Survey held at *London* Date, first Survey *4th April* Last Survey *25th April* 18 *77*
101 on the *"Condignion"* Master *Richardson*
 Tonnage *781* Built at *Glasgow* When built *1869*
 By whom built *Laurie* Owners *Annand*
 Port belonging to *London* Destined Voyage
 If Surveyed Afloat or in Dry Dock *Fletcher's dock*

Last Survey, No. *15913* Port of *Iron*

Classed *100 A1*
 Years assigned. *3.76*
 Character in Register Book. *S.P. 184.74*

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treeails Quite
 Breasthooks and Stemson *de de*
 Transoms, Pointers, and Crutches *de de*
 Timbers of the Frame at the Opening *de de*
 Ditto ditto at other places *de de*
 Keelsons *de de*
 Clamps and Shelves *de de*
 Ceiling *de de*
 Rudder *de*
 Copper or Y.M. *—* When put on *—*
 Caulking of Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

good

and

complete

Bottom recoated. Rudder pintles

made good. This vessel appears in good condition and eligible to remain as classed.

Committee's Minute *8th May* 18 *77*

Character assigned *100 A1*

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

IRON 471-0384

Calculus

Erasmus



© 2019

Lloyd's Register
Foundation